

序号	报告编号	发布日期	结论	影像资料
235	GX-B1363/22-A-23359	2023/8/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
236	GX-B1363/22-A-23358	2023/8/23	所检项目合格。	 <p>The photograph shows two men in light blue work shirts inspecting a large, rusted metal cabinet. A vertical pipe extends from the top of the cabinet. One man is on the left, looking at the cabinet, while the other is on the right, wearing gloves and looking at a panel. A green trash bin is visible on the left. A date stamp '2023/08/18' is in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
237	GX-B1363/22-A-23357	2023/8/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
238	GX-B1364/22-A-23771	2023/8/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
239	GX-B1364/22-A-23770	2023/8/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
240	GX-B1364/22-A-23769	2023/8/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
241	GX-B1364/22-A-23768	2023/8/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
242	GX-B1364/22-A-23767	2023/8/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
243	GX-B1364/22-A-23766	2023/8/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
244	GX-B1363/22-A-23352	2023/8/28	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
245	GX-B1363/22-A-23369	2023/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
246	GX-B1363/22-A-23370	2023/8/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
247	GX-B1366/20-A-23095	2023/8/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
248	GX-B1365/20-A-23063	2023/8/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
249	GX-B1366/20-A-23096	2023/8/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
250	GX-B1365/20-A-23062	2023/8/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
251	GX-B1509/20-A-23010	2023/8/24	所检项目合格。	 <p>2023/08/11</p>

序号	报告编号	发布日期	结论	影像资料
252	GX-B1363/22-A-23356	2023/8/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
253	GX-B1367/22-A-23085	2023/8/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
254	GX-B1363/22-A-23336	2023/8/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
255	GX-B1363/22-A-23333	2023/8/28	所检项目合格。	 <p>2023/07/31</p>

序号	报告编号	发布日期	结论	影像资料
256	GX-B1363/22-A-23331	2023/8/28	所检项目合格。	 A photograph showing two male technicians in light blue work shirts inspecting a large, rusted industrial furnace. The furnace has a tall, cylindrical chimney pipe extending upwards. One technician is on the left, looking at the furnace, while the other is on the right, wearing gloves and touching the furnace door. The furnace has yellow warning labels. A date stamp '2023/07/28' is visible in the bottom right corner of the photo. The background shows a window with a view of greenery outside.

序号	报告编号	发布日期	结论	影像资料
257	GX-B1363/22-A-23329	2023/8/28	所检项目合格。	 A photograph showing two men in light blue work shirts inspecting a large, dark-colored industrial furnace. The furnace has a tall, white, cylindrical chimney pipe extending from its top. One man is on the left, wearing glasses and a black glove, looking at the furnace. The other man is on the right, looking into the open door of the furnace. A green trash bin is visible on the left. A date stamp '2023/07/25' is overlaid in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
258	GX-B1363/22-A-23328	2023/8/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
259	GX-B1365/20-A-23059	2023/8/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
260	GX-B1366/20-A-23092	2023/8/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
261	GX-B1363/22-A-23318	2023/8/28	所检项目合格。	 <p>The photograph shows two men in light blue work shirts inspecting a large, rusted metal cabinet. One man is on the left, looking into an open compartment. The other man is on the right, wearing a grey glove and looking at the cabinet's interior. A large black industrial fan is visible on the right side of the frame. The date '2023/07/19' is printed in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
262	GX-B1363/22-A-23326	2023/8/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
263	GX-B1363/22-A-23327	2023/8/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
264	GX-B1364/22-A-23781	2023/8/31	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
265	GX-B1364/22-A-23782	2023/8/31	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
266	GX-B1364/22-A-23748	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
267	GX-B1364/22-A-23758	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
268	GX-B1364/22-A-23759	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
269	GX-B1364/22-A-23752	2023/8/29	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
270	GX-B1364/22-A-23755	2023/8/29	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
271	GX-B1364/22-A-23756	2023/8/29	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
272	GX-B1364/22-A-23757	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
273	GX-B1364/22-A-23765	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
274	GX-B1369/20-A-23009	2023/8/31	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
275	GX-B1369/20-A-23008	2023/8/31	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
276	GX-B1365/20-A-23060	2023/8/29	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
277	GX-B1366/20-A-23094	2023/8/29	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
278	GX-B1364/22-A-23751	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
279	GX-B1364/22-A-23747	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
280	GX-B1364/22-A-23772	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
281	GX-B1364/22-A-23773	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
282	GX-B1364/22-A-23749	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
283	GX-B1364/22-A-23760	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
284	GX-B1364/22-A-23761	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
285	GX-B1364/22-A-23762	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
286	GX-B1364/22-A-23763	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
287	GX-B1364/22-A-23764	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
288	GX-B1364/22-A-23754	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
289	GX-B1364/22-A-23750	2023/8/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
290	GX-B1364/22-A-23753	2023/8/29	所检项目合格。	