

序号	报告编号	发布日期	结论	影像资料
132	GX-B1363/22-A-22457	2022/11/21	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
133	GX-B1363/22-A-22458	2022/11/21	所检项目合格	 <p>2022/11/17</p>

序号	报告编号	发布日期	结论	影像资料
134	GX-B1363/22-A-22453	2022/11/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
135	GX-B1363/22-A-22454	2022/11/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
136	GX-B1363/22-A-22459	2022/11/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
137	GX-B1367/22-A-22109	2022/11/25	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
138	GX-B1363/22-A-22445	2022/11/25	所检项目合格	 A photograph showing two technicians in a dark jacket and safety gloves inspecting a large, industrial furnace. The furnace has a large, cylindrical top section and a rectangular body with two doors. One door is open, and the technician on the right is looking inside. The furnace has yellow warning labels. The background shows a window with trees outside. A date stamp '2022/10/22' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
139	GX-B1363/22-A-22446	2022/11/25	所检项目合格	



序号	报告编号	发布日期	结论	影像资料
140	GX-B1363/22-A-22447	2022/11/25	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
141	GX-B1363/22-A-22448	2022/11/25	所检项目合格	 <p>2022/10/27</p>

序号	报告编号	发布日期	结论	影像资料
142	GX-B1508/20-A-22011	2022/11/25	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
143	GX-B1363/22-A-22467	2022/11/30	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
144	GX-B1365/20-A-22105	2022/12/1	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
145	GX-B1363/22-A-22465	2022/11/30	所检项目合格	 <p>The photograph captures two individuals, likely technicians, engaged in an inspection of a large, industrial-grade electrical cabinet. They are wearing light-colored, possibly white, work uniforms. The cabinet is a complex piece of equipment with multiple compartments and a prominent white cylindrical structure on top. The doors of the cabinet are open, and the technicians are leaning in to examine the internal components. The setting appears to be an indoor facility, possibly a control room or a technical area, with a window in the background showing some outdoor greenery. A date stamp '2022/11/25' is overlaid on the bottom right of the image.</p>

序号	报告编号	发布日期	结论	影像资料
146	GX-B1363/22-A-22464	2022/11/30	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
147	GX-B1363/22-A-22455	2022/11/30	所检项目合格	



序号	报告编号	发布日期	结论	影像资料
148	GX-B1363/22-A-22456	2022/11/30	所检项目合格	 A photograph showing two men in grey work jackets inspecting a large, weathered metal cabinet. One man is wearing yellow and red gloves. To the left is a green trash bin. A date stamp '2022/11/24' is visible in the bottom right corner of the photo. The cabinet has a yellow warning triangle on its door.