

序号	报告编号	发布日期	结论	影像资料
60	GX-B1539/22-Y-22210	2023年1月14日	所检项目合格	
61	GX-B1522/20-Y-22080	2023年1月14日	所检项目合格	
62	GX-B1522/20-Y-22081	2023年1月14日	所检项目合格	

63	GX-B1522/20-Y-22082	2023年1月14日	所检项目合格	
64	GX-B1522/20-Y-22083	2023年1月14日	所检项目合格	
65	GX-B1522/20-Y-22084	2023年1月14日	所检项目合格	
66	GX-B1522/20-Y-22085	2023年1月14日	所检项目合格	

67	GX-B1522/20-Y-22086	2023年1月14日	所检项目合格	 A yellow tracked excavator is shown in a desert environment. The machine is positioned on a dirt path, and a person is standing nearby. The background shows a clear blue sky and some distant structures. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the image.
68	GX-B1522/20-Y-22087	2023年1月14日	所检项目合格	 A yellow tracked excavator is shown in a snowy environment. The machine is positioned on a snow-covered ground, and a person is standing nearby. The background shows a clear blue sky and some distant structures. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the image.
69	GX-B1521/20-Y-22303	2023年1月14日	所检项目合格	 A yellow tracked excavator is shown in a desert environment. The machine is positioned on a dirt path, and a person is standing nearby. The background shows a clear blue sky and some distant structures. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the image.
70	GX-B1521/20-Y-22304	2023年1月14日	所检项目合格	 A yellow tracked excavator is shown in a snowy environment. The machine is positioned on a snow-covered ground, and a person is standing nearby. The background shows a clear blue sky and some distant structures. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the image.

71	GX-B1423/20-Y-223542	2023年1月14日	合格	
72	GX-B1521/20-Y-23024	2023/1/14	所检项目合格	
73	GX-B1521/20-Y-23025	2023/1/14	所检项目合格	
74	GX-B1522/20-Y-23001	2023/1/14	所检项目合格	

75	GX-B1522/20-Y-23002	2023/1/14	所检项目合格	
76	GX-B1522/20-Y-23003	2023/1/14	所检项目合格	
77	GX-B1522/20-Y-23004	2023/1/14	所检项目合格	
78	GX-B1522/20-Y-23005	2023/1/14	所检项目合格	

79	GX-B1522/20-Y-23006	2023/1/14	所检项目合格	
80	GX-B1522/20-Y-23007	2023/1/14	所检项目合格	
81	GX-B1522/20-Y-23008	2023/1/14	所检项目合格	
82	GX-B1522/20-Y-23009	2023/1/14	所检项目合格	

83	GX-B1522/20-Y-23010	2023/1/14	所检项目合格	
84	GX-B1521/20-Y-22320	2023/1/14	所检项目合格	
85	GX-B1521/20-Y-22321	2023/1/14	所检项目合格	
86	GX-B1521/20-Y-22322	2023/1/14	所检项目合格	

87	GX-B1521/20-Y-22323	2023/1/14	所检项目合格	 A yellow excavator is shown in a dark, possibly underground or night-time setting. The bucket is raised, and a person is standing near the base of the machine. A date stamp '2022/12/28' is visible in the bottom right corner of the image.
88	GX-B1521/20-Y-22324	2023/1/14	所检项目合格	 A yellow excavator is shown in a dark setting. The bucket is lowered to the ground. A person is standing next to the machine. A date stamp '2022/12/28' is visible in the bottom right corner of the image.
89	GX-B1521/20-Y-22325	2023/1/14	所检项目合格	 A yellow excavator is shown in a dark setting. The bucket is raised. A person is standing near the machine. A date stamp '2022/12/28' is visible in the bottom right corner of the image.
90	GX-B1521/20-Y-22326	2023/1/14	所检项目合格	 A yellow excavator is shown in a dark setting. The bucket is lowered. A person is standing near the machine. A date stamp '2022/12/28' is visible in the bottom right corner of the image.

91	GX-B1521/20-Y-22327	2023/1/14	所检项目合格	 A yellow excavator is shown at a construction site during dusk. A person in a white protective suit stands near the machine. A yellow timestamp '2022/12/28' is visible in the bottom right corner of the photo.
92	GX-B1521/20-Y-22328	2023/1/14	所检项目合格	 A yellow excavator is shown at a construction site during dusk. A yellow timestamp '2022/12/28' is visible in the bottom right corner of the photo.
93	GX-B1521/20-Y-22329	2023/1/14	所检项目合格	 A yellow excavator is shown at a construction site during dusk. A yellow timestamp '2022/12/28' is visible in the bottom right corner of the photo.
94	GX-B1521/20-Y-22330	2023/1/14	所检项目合格	 A yellow excavator is shown at a construction site during dusk. A yellow timestamp '2022/12/28' is visible in the bottom right corner of the photo.

95	GX-B1521/20-Y-22331	2023/1/14	所检项目合格	
96	GX-B1539/22-Y-22200	2023/1/14	所检项目合格	
97	GX-B1539/22-Y-22201	2023/1/14	所检项目合格	
98	GX-B1539/22-Y-22202	2023/1/14	所检项目合格	

99	GX-B1539/22-Y-22203	2023/1/14	所检项目合格	
100	GX-B1539/22-Y-22204	2023/1/14	所检项目合格	
101	GX-B1539/22-Y-22205	2023/1/14	所检项目合格	
102	GX-B1539/22-Y-22206	2023/1/14	所检项目合格	

103	GX-B1539/22-Y-22207	2023/1/14	所检项目合格	 A yellow wheel loader is parked on a dirt surface under a clear blue sky. A person is standing near the front of the machine. A yellow timestamp '2023-12-31' is visible in the bottom right corner of the photo.
104	GX-B1539/22-Y-22208	2023/1/14	所检项目合格	 A yellow wheel loader with a forklift attachment is parked on a dirt surface. A person is standing next to it. A yellow timestamp '2023-12-31' is visible in the bottom right corner of the photo.
105	GX-B1539/22-Y-22209	2023/1/14	所检项目合格	 A yellow wheel loader is parked on a dirt surface. A person is standing near the front. A yellow timestamp '2023-12-31' is visible in the bottom right corner of the photo.
106	GX-B1557/22-Y-22008	2023/1/14	所检项目合格	 A yellow wheel loader is parked on a dirt surface. A person is standing near the front. A yellow timestamp '2023-12-31' is visible in the bottom right corner of the photo.

107	GX-B1557/22-Y-22009	2023/1/14	所检项目合格	
108	GX-B1557/22-Y-22010	2023/1/14	所检项目合格	
109	GX-B1556/22-Y-22002	2023/1/14	所检项目合格	
110	GX-B1556/22-Y-22003	2023/1/14	所检项目合格	

111	GX-B1521/20-Y-23001	2023/1/14	所检项目合格	
112	GX-B1521/20-Y-23002	2023/1/14	所检项目合格	
113	GX-B1521/20-Y-23003	2023/1/14	所检项目合格	
114	GX-B1521/20-Y-23004	2023/1/14	所检项目合格	

115	GX-B1521/20-Y-23005	2023/1/14	所检项目合格	 A yellow excavator is shown in a construction or mining environment. The background is bright, suggesting a sunny day. A small yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
116	GX-B1521/20-Y-23006	2023/1/14	所检项目合格	 A yellow excavator is shown in a dark, possibly underground or night-time setting. The lighting is dim, highlighting the machine's silhouette. A small yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
117	GX-B1521/20-Y-23007	2023/1/14	所检项目合格	 A yellow excavator is shown in a dusty or smoky environment, possibly during a mining operation. The background is hazy. A small yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
118	GX-B1521/20-Y-23008	2023/1/14	所检项目合格	 A yellow excavator is shown in a dark, rocky environment, likely a mine. The lighting is low, with some highlights on the machine. A small yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.

119	GX-B1521/20-Y-23009	2023/1/14	所检项目合格	 A yellow excavator is shown in a construction or mining site, with its bucket raised. The background is a hazy, overcast sky. A small yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
120	GX-B1521/20-Y-23010	2023/1/14	所检项目合格	 A yellow excavator is shown in a construction or mining site, with its bucket lowered. The background is a hazy, overcast sky. A small yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
121	GX-B1521/20-Y-23011	2023/1/14	所检项目合格	 A yellow excavator is shown in a construction or mining site, with its bucket raised. The background is a hazy, overcast sky. A small yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
122	GX-B1521/20-Y-23012	2023/1/14	所检项目合格	 A yellow excavator is shown in a construction or mining site, with its bucket lowered. The background is a hazy, overcast sky. A small yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.

123	GX-B1521/20-Y-23013	2023/1/14	所检项目合格	 A yellow excavator is shown in a snowy field. The excavator's arm is raised, and it appears to be in operation or recently used. The ground is covered in snow, and there are some dark patches, possibly from the excavator's tracks or tires. A yellow timestamp '2023-1-13' is visible in the bottom right corner of the image.
124	GX-B1521/20-Y-23014	2023/1/14	所检项目合格	 A yellow excavator is positioned on a dirt road or construction site. The excavator's arm is extended, and it is facing towards the right. The background shows a clear sky and some distant structures. A yellow timestamp '2023-1-13' is visible in the bottom right corner of the image.
125	GX-B1521/20-Y-23015	2023/1/14	所检项目合格	 A yellow excavator is shown with its bucket raised, dumping material into a large container or truck. The excavator is positioned on a dirt surface, and the background is a bright, hazy sky. A yellow timestamp '2023-1-13' is visible in the bottom right corner of the image.
126	GX-B1521/20-Y-23016	2023/1/14	所检项目合格	 A yellow excavator is shown in an open field, possibly a construction site. The excavator's arm is raised, and it is facing towards the right. The ground is a mix of dirt and snow. A yellow timestamp '2023-1-13' is visible in the bottom right corner of the image.

127	GX-B1521/20-Y-23023	2023/1/14	所检项目合格	
128	GX-B1423/20-Y-23001	2023/1/14	合格	
129	GX-B1423/20-Y-23002	2023/1/14	合格	
130	GX-B1423/20-Y-23003	2023/1/14	合格	

131	GX-B1423/20-Y-23004	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a yellow body and a white cab. The date '2023-1-14' is visible in the bottom right corner of the image.
132	GX-B1423/20-Y-23005	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a yellow body and a white cab. The date '2023-1-14' is visible in the bottom right corner of the image.
133	GX-B1423/20-Y-23006	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a yellow body and a white cab. The date '2023-1-14' is visible in the bottom right corner of the image.
134	GX-B1423/20-Y-23007	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a yellow body and a white cab. The date '2023-1-14' is visible in the bottom right corner of the image.

135	GX-B1423/20-Y-23008	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck, and another worker is visible near the rear. The truck's bed is raised. A yellow timestamp '2023-1-14' is visible in the bottom right corner of the photo.
136	GX-B1423/20-Y-23009	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck, and another worker is visible near the rear. The truck's bed is raised. A yellow timestamp '2023-1-14' is visible in the bottom right corner of the photo.
137	GX-B1423/20-Y-23010	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck, and another worker is visible near the rear. The truck's bed is raised. A yellow timestamp '2023-1-14' is visible in the bottom right corner of the photo.
138	GX-B1423/20-Y-23011	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck, and another worker is visible near the rear. The truck's bed is raised. A yellow timestamp '2023-1-14' is visible in the bottom right corner of the photo.

139	GX-B1423/20-Y-23012	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. A person is standing near the front of the truck. The truck's bed is raised. A date stamp '2023-1-14' is visible in the bottom right corner of the image.
140	GX-B1423/20-Y-23013	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. A person is standing near the front of the truck. The truck's bed is raised. A date stamp '2023-1-14' is visible in the bottom right corner of the image.
141	GX-B1423/20-Y-23014	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. A person is standing near the front of the truck. The truck's bed is raised. A date stamp '2023-1-14' is visible in the bottom right corner of the image.
142	GX-B1423/20-Y-23015	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. A person is standing near the front of the truck. The truck's bed is raised. A date stamp '2023-1-14' is visible in the bottom right corner of the image.





143	GX-B1423/20-Y-23016	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in orange safety gear are standing near the front of the truck. The truck's bed is raised. A date stamp '2023/1/14' is visible in the bottom right corner of the image.
144	GX-B1423/20-Y-23017	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in orange safety gear are standing near the front of the truck. The truck's bed is raised. A date stamp '2023/1/14' is visible in the bottom right corner of the image.
145	GX-B1423/20-Y-23018	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in orange safety gear are standing near the front of the truck. The truck's bed is raised. A date stamp '2023/1/14' is visible in the bottom right corner of the image.
146	GX-B1423/20-Y-23019	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in orange safety gear are standing near the front of the truck. The truck's bed is raised. A date stamp '2023/1/14' is visible in the bottom right corner of the image.

147	GX-B1423/20-Y-23020	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a dirt surface. A person in a high-visibility vest stands near the front. A yellow timestamp '2023/1/2' is in the bottom right corner.
148	GX-B1423/20-Y-23021	2023/1/14	合格	 A yellow dump truck parked on a snow-covered ground. The bed is slightly raised. A person is visible near the front. A yellow timestamp '2023/1/2' is in the bottom right corner.
149	GX-B1423/20-Y-23022	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a dirt surface. A person is standing near the front. A yellow timestamp '2023/1/2' is in the bottom right corner.
150	GX-B1423/20-Y-23023	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a dirt surface. A person is standing near the front. A yellow timestamp '2023/1/2' is in the bottom right corner.





151	GX-B1423/20-Y-23024	2023/1/14	合格	 A yellow dump truck with the number 108 on its side, parked on a snowy ground. A person is standing near the front. A yellow timestamp '2023/1/2' is in the bottom right corner.
152	GX-B1423/20-Y-23025	2023/1/14	合格	 A yellow dump truck with its bucket raised, parked on a snowy ground. A person is standing near the front. A yellow timestamp '2023/1/2' is in the bottom right corner.
153	GX-B1423/20-Y-23026	2023/1/14	合格	 A yellow dump truck with its bucket raised, parked on a snowy ground. A person is standing near the front. A yellow timestamp '2023/1/2' is in the bottom right corner.
154	GX-B1423/20-Y-23027	2023/1/14	合格	 A yellow dump truck with its bucket raised, parked on a snowy ground. A person is standing near the front. A yellow timestamp '2023/1/2' is in the bottom right corner.

155	GX-B1423/20-Y-23028	2023/1/14	合格	
156	GX-B1423/20-Y-23029	2023/1/14	合格	
157	GX-B1423/20-Y-23030	2023/1/14	合格	
158	GX-B1423/20-Y-223419	2023/1/14	合格	

159	GX-B1423/20-Y-223420	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a snowy field. A person is standing near the rear of the truck. A timestamp '2022/12/22' is visible in the bottom right corner.
160	GX-B1423/20-Y-223421	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a snowy field. A person is standing near the rear of the truck. A timestamp '2022/12/22' is visible in the bottom right corner.
161	GX-B1423/20-Y-223422	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a snowy field. A person is standing near the rear of the truck. A timestamp '2022/12/22' is visible in the bottom right corner.
162	GX-B1423/20-Y-223423	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a snowy field. A person is standing near the rear of the truck. A timestamp '2022/12/22' is visible in the bottom right corner.

163	GX-B1423/20-Y-223424	2023/1/14	合格	
164	GX-B1423/20-Y-223425	2023/1/14	合格	
165	GX-B1423/20-Y-223426	2023/1/14	合格	
166	GX-B1423/20-Y-223427	2023/1/14	合格	


167	GX-B1423/20-Y-223428	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front. A yellow timestamp '2022/12/22' is in the bottom right corner.
168	GX-B1423/20-Y-223429	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front. A yellow timestamp '2022/12/22' is in the bottom right corner.
169	GX-B1423/20-Y-223430	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front. A yellow timestamp '2022/12/22' is in the bottom right corner.
170	GX-B1423/20-Y-223431	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front. A yellow timestamp '2022/12/22' is in the bottom right corner.





171	GX-B1423/20-Y-223432	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person is visible near the front. A yellow timestamp '2022/12/23' is in the bottom right corner.
172	GX-B1423/20-Y-223433	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person is visible near the front. A yellow timestamp '2022/12/23' is in the bottom right corner.
173	GX-B1423/20-Y-223434	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person is visible near the front. A yellow timestamp '2022/12/23' is in the bottom right corner.
174	GX-B1423/20-Y-223435	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person is visible near the front. A yellow timestamp '2022/12/23' is in the bottom right corner.

175	GX-B1423/20-Y-223436	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, sandy surface. A person is standing near the front of the truck. The date 2022/12/23 is visible in the bottom right corner of the image.
176	GX-B1423/20-Y-223437	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, sandy surface. A person is standing near the front of the truck. The date 2022/12/23 is visible in the bottom right corner of the image.
177	GX-B1423/20-Y-223438	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, sandy surface. A person is standing near the front of the truck. The date 2022/12/23 is visible in the bottom right corner of the image.
178	GX-B1423/20-Y-223439	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, sandy surface. A person is standing near the front of the truck. The date 2022/12/23 is visible in the bottom right corner of the image.

179	GX-B1423/20-Y-223440	2023/1/14	合格	
180	GX-B1423/20-Y-223441	2023/1/14	合格	
181	GX-B1423/20-Y-223442	2023/1/14	合格	
182	GX-B1423/20-Y-223443	2023/1/14	合格	

183	GX-B1423/20-Y-223444	2023/1/14	合格	
184	GX-B1423/20-Y-223445	2023/1/14	合格	
185	GX-B1423/20-Y-223446	2023/1/14	合格	
186	GX-B1423/20-Y-223447	2023/1/14	合格	

187	GX-B1423/20-Y-223448	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front. The date stamp '2022/12/24' is visible in the bottom right corner.
188	GX-B1423/20-Y-223449	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front. The date stamp '2022/12/24' is visible in the bottom right corner.
189	GX-B1423/20-Y-223450	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front. The date stamp '2022/12/24' is visible in the bottom right corner.
190	GX-B1423/20-Y-223451	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front. The date stamp '2022/12/24' is visible in the bottom right corner.

191	GX-B1423/20-Y-223452	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. The truck is viewed from a side-rear angle. A person is standing near the front. The date '2022/12/24' is visible in the bottom right corner of the image.
192	GX-B1423/20-Y-223453	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. The truck is viewed from a side-rear angle. A person is standing near the front. The date '2022/12/24' is visible in the bottom right corner of the image.
193	GX-B1423/20-Y-223454	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. The truck is viewed from a side-rear angle. A person is standing near the front. The date '2022/12/24' is visible in the bottom right corner of the image.
194	GX-B1423/20-Y-223455	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. The truck is viewed from a side-rear angle. A person is standing near the front. The date '2022/12/24' is visible in the bottom right corner of the image.

195	GX-B1423/20-Y-223456	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. The truck is viewed from a side-rear angle. A person is standing near the front. A yellow timestamp '2022/12/24' is in the bottom right corner.
196	GX-B1423/20-Y-223457	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. The truck is viewed from a side-rear angle. A person is standing near the front. A yellow timestamp '2022/12/24' is in the bottom right corner.
197	GX-B1423/20-Y-223458	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. The truck is viewed from a side-rear angle. A person is standing near the front. A yellow timestamp '2022/12/24' is in the bottom right corner.
198	GX-B1423/20-Y-223459	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a flat, light-colored surface. The truck is viewed from a side-rear angle. A person is standing near the front. A yellow timestamp '2022/12/24' is in the bottom right corner.





199	GX-B1423/20-Y-223460	2023/1/14	合格	 A yellow dump truck is parked on a flat, sandy surface under a clear blue sky. A person in a green safety vest is standing near the front of the truck. The truck's bed is slightly raised. A yellow timestamp '2022/12/25' is visible in the bottom right corner of the photo.
200	GX-B1423/20-Y-223461	2023/1/14	合格	 A yellow dump truck is parked on a flat, sandy surface under a clear blue sky. A person is standing near the front of the truck. The truck's bed is slightly raised. A yellow timestamp '2022/12/25' is visible in the bottom right corner of the photo.
201	GX-B1423/20-Y-223462	2023/1/14	合格	 A yellow dump truck is parked on a flat, sandy surface under a clear blue sky. A person in a green safety vest is standing near the front of the truck. The truck's bed is slightly raised. A yellow timestamp '2022/12/25' is visible in the bottom right corner of the photo.
202	GX-B1423/20-Y-223463	2023/1/14	合格	 A yellow dump truck is parked on a flat, sandy surface under a clear blue sky. A person is standing near the front of the truck. The truck's bed is slightly raised. A yellow timestamp '2022/12/25' is visible in the bottom right corner of the photo.





203	GX-B1423/20-Y-223464	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective, parked on a flat, light-colored surface under a clear blue sky. The truck's bed is slightly raised. A yellow timestamp '2022/12/25' is visible in the bottom right corner of the image.
204	GX-B1423/20-Y-223465	2023/1/14	合格	 A yellow dump truck is shown from a side-front perspective. A person in a light-colored uniform stands to the right of the truck, facing it. The truck is parked on a flat, light-colored surface. A yellow timestamp '2022/12/25' is visible in the bottom right corner of the image.
205	GX-B1423/20-Y-223466	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective. A person in a light-colored uniform stands to the right of the truck, facing it. The truck is parked on a flat, light-colored surface. A yellow timestamp '2022/12/25' is visible in the bottom right corner of the image.
206	GX-B1423/20-Y-223467	2023/1/14	合格	 A yellow dump truck is shown from a side-front perspective. A person in a light-colored uniform stands to the left of the truck, facing it. The truck is parked on a flat, light-colored surface. A yellow timestamp '2022/12/25' is visible in the bottom right corner of the image.





207	GX-B1423/20-Y-223468	2023/1/14	合格	
208	GX-B1423/20-Y-223469	2023/1/14	合格	
209	GX-B1423/20-Y-223470	2023/1/14	合格	
210	GX-B1423/20-Y-223471	2023/1/14	合格	

211	GX-B1423/20-Y-223472	2023/1/14	合格	 A yellow dump truck is parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front of the truck. The truck's bed is slightly raised. A yellow timestamp '2022/12/26' is visible in the bottom right corner of the photo.
212	GX-B1423/20-Y-223473	2023/1/14	合格	 A yellow dump truck is parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front of the truck. The truck's bed is slightly raised. A yellow timestamp '2022/12/26' is visible in the bottom right corner of the photo.
213	GX-B1423/20-Y-223474	2023/1/14	合格	 A yellow dump truck is parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front of the truck. The truck's bed is slightly raised. A yellow timestamp '2022/12/26' is visible in the bottom right corner of the photo.
214	GX-B1423/20-Y-223475	2023/1/14	合格	 A yellow dump truck is parked on a flat, light-colored surface. A person in a high-visibility vest is standing near the front of the truck. The truck's bed is slightly raised. A yellow timestamp '2022/12/26' is visible in the bottom right corner of the photo.

215	GX-B1423/20-Y-223476	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective with its bed raised. The truck is parked on a flat, sandy surface under a clear blue sky. A person in a high-visibility vest is standing near the front of the truck. A date stamp '2022/12/26' is visible in the bottom right corner of the image.
216	GX-B1423/20-Y-223477	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective with its bed raised. The truck is parked on a flat, sandy surface under a clear blue sky. A person in a high-visibility vest is standing near the front of the truck. A date stamp '2022/12/26' is visible in the bottom right corner of the image.
217	GX-B1423/20-Y-223478	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective with its bed raised. The truck is parked on a flat, sandy surface under a clear blue sky. A person in a high-visibility vest is standing near the front of the truck. A date stamp '2022/12/26' is visible in the bottom right corner of the image.
218	GX-B1423/20-Y-223479	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective with its bed raised. The truck is parked on a flat, sandy surface under a clear blue sky. A person in a high-visibility vest is standing near the front of the truck. A date stamp '2022/12/26' is visible in the bottom right corner of the image.

219	GX-B1423/20-Y-223480	2023/1/14	合格	 A yellow dump truck is parked on a paved surface. The truck is viewed from a side-rear angle. A person in a high-visibility vest is standing near the front. A timestamp '2022-12-26' is visible in the bottom right corner of the image.
220	GX-B1423/20-Y-223481	2023/1/14	合格	 A yellow dump truck is parked on a paved surface. The truck is viewed from a side-rear angle. A person in a high-visibility vest is standing near the front. A timestamp '2022-12-26' is visible in the bottom right corner of the image.
221	GX-B1423/20-Y-223482	2023/1/14	合格	 A yellow dump truck is parked on a paved surface. The truck is viewed from a side-rear angle. A person in a high-visibility vest is standing near the front. A timestamp '2022-12-26' is visible in the bottom right corner of the image.
222	GX-B1423/20-Y-223483	2023/1/14	合格	 A yellow dump truck is parked on a paved surface. The truck is viewed from a side-rear angle. A person in a high-visibility vest is standing near the front. A timestamp '2022-12-26' is visible in the bottom right corner of the image.

223	GX-B1423/20-Y-223484	2023/1/14	合格	
224	GX-B1423/20-Y-223485	2023/1/14	合格	
225	GX-B1423/20-Y-223486	2023/1/14	合格	
226	GX-B1423/20-Y-223487	2023/1/14	合格	

227	GX-B1423/20-Y-223488	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. A person in a high-visibility vest is standing near the front. The truck's bed is slightly raised. A date stamp '2022-12-27' is visible in the bottom right corner.
228	GX-B1423/20-Y-223489	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. A person in a high-visibility vest is standing near the front. The truck's bed is slightly raised. A date stamp '2022-12-27' is visible in the bottom right corner.
229	GX-B1423/20-Y-223490	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. A person in a high-visibility vest is standing near the front. The truck's bed is slightly raised. A date stamp '2022-12-27' is visible in the bottom right corner.
230	GX-B1423/20-Y-223491	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. A person in a high-visibility vest is standing near the front. The truck's bed is slightly raised. A date stamp '2022-12-27' is visible in the bottom right corner.

231	GX-B1423/20-Y-223492	2023/1/14	合格	 A yellow dump truck is shown from a rear-quarter perspective. The truck is parked on a light-colored, possibly sandy or gravelly surface. A person in a high-visibility vest is standing near the rear wheel. The date stamp '2022-12-27' is visible in the bottom right corner of the image.
232	GX-B1423/20-Y-223493	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective. The truck is parked on a dirt or gravel surface. A person in a high-visibility vest is standing near the rear wheel. The date stamp '2022-12-27' is visible in the bottom right corner of the image.
233	GX-B1423/20-Y-223494	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective. The truck is parked on a dirt or gravel surface. A person in a high-visibility vest is standing near the rear wheel. The date stamp '2022-12-27' is visible in the bottom right corner of the image.
234	GX-B1423/20-Y-223495	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective. The truck is parked on a dirt or gravel surface. A person in a high-visibility vest is standing near the rear wheel. The date stamp '2022-12-27' is visible in the bottom right corner of the image.

235	GX-B1423/20-Y-223496	2023/1/14	合格	 A yellow dump truck is parked on a dirt lot under a clear blue sky. Two people are standing near the front of the truck. A timestamp '2022/12/27' is visible in the bottom right corner of the photo.
236	GX-B1423/20-Y-223497	2023/1/14	合格	 A yellow dump truck is parked on a dirt lot under a clear blue sky. Two people are standing near the front of the truck. A timestamp '2022/12/27' is visible in the bottom right corner of the photo.
237	GX-B1423/20-Y-223498	2023/1/14	合格	 A yellow dump truck is parked on a dirt lot under a clear blue sky. Two people are standing near the front of the truck. A timestamp '2022/12/27' is visible in the bottom right corner of the photo.
238	GX-B1423/20-Y-223499	2023/1/14	合格	 A yellow dump truck is parked on a dirt lot under a clear blue sky. Two people are standing near the front of the truck. A timestamp '2022/12/28' is visible in the bottom right corner of the photo.

239	GX-B1423/20-Y-223500	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck, and another worker is near the rear. A small black box and other equipment are on the ground in front of the truck. A yellow timestamp '2022-12-28' is visible in the bottom right corner of the photo.
240	GX-B1423/20-Y-223501	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck, and another worker is near the rear. A small black box and other equipment are on the ground in front of the truck. A yellow timestamp '2022-12-28' is visible in the bottom right corner of the photo.
241	GX-B1423/20-Y-223502	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck, and another worker is near the rear. A small black box and other equipment are on the ground in front of the truck. A yellow timestamp '2022-12-28' is visible in the bottom right corner of the photo.
242	GX-B1423/20-Y-223503	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck, and another worker is near the rear. A small black box and other equipment are on the ground in front of the truck. A yellow timestamp '2022-12-28' is visible in the bottom right corner of the photo.

243	GX-B1423/20-Y-223504	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. A person is standing near the front of the truck. The truck's bed is slightly raised. A timestamp '2023-12-28' is visible in the bottom right corner of the image.
244	GX-B1423/20-Y-223505	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. A person is standing near the front of the truck. The truck's bed is slightly raised. A timestamp '2023-12-28' is visible in the bottom right corner of the image.
245	GX-B1423/20-Y-223506	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. A person is standing near the front of the truck. The truck's bed is slightly raised. A timestamp '2023-12-28' is visible in the bottom right corner of the image.
246	GX-B1423/20-Y-223507	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. A person is standing near the front of the truck. The truck's bed is slightly raised. A timestamp '2023-12-28' is visible in the bottom right corner of the image.

247	GX-B1423/20-Y-223508	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. A timestamp in the bottom right corner reads "2023/1/28".
248	GX-B1423/20-Y-223509	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. A timestamp in the bottom right corner reads "2023/1/28".
249	GX-B1423/20-Y-223510	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. A timestamp in the bottom right corner reads "2023/12/28".
250	GX-B1423/20-Y-223511	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. A timestamp in the bottom right corner reads "2023/12/28".

251	GX-B1423/20-Y-223512	2023年1月14日	合格	 A yellow truck with a red flag on top, parked on a snowy surface. Two workers in orange safety gear are standing in front of the truck. A timestamp '2023-1-14' is visible in the bottom right corner of the photo.
252	GX-B1423/20-Y-223513	2023年1月14日	合格	 A yellow truck with a red flag on top, parked on a snowy surface. Two workers in orange safety gear are standing in front of the truck. A timestamp '2023-1-14' is visible in the bottom right corner of the photo.
253	GX-B1423/20-Y-223514	2023年1月14日	合格	 A yellow truck with a red flag on top, parked on a snowy surface. Two workers in orange safety gear are standing in front of the truck. A timestamp '2023-1-14' is visible in the bottom right corner of the photo.
254	GX-B1423/20-Y-223515	2023年1月14日	合格	 A yellow truck with a red flag on top, parked on a snowy surface. Two workers in orange safety gear are standing in front of the truck. A timestamp '2023-1-14' is visible in the bottom right corner of the photo.

255	GX-B1423/20-Y-223516	2023年1月14日	合格	 A yellow truck is parked on a dirt road. Two workers in orange safety gear are standing in front of it. The truck has a red flag on its roof. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
256	GX-B1423/20-Y-223517	2023年1月14日	合格	 A yellow truck is parked on a dirt road. Two workers in orange safety gear are standing in front of it. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
257	GX-B1423/20-Y-223543	2023年1月14日	合格	 A green truck is parked on a dirt road. Two workers in safety gear are standing in front of it. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
258	GX-B1423/20-Y-223544	2023年1月14日	合格	 A green truck is parked on a dirt road. Two workers in safety gear are standing in front of it. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.

259	GX-B1423/20-Y-223545	2023年1月14日	合格	
260	GX-B1423/20-Y-223546	2023年1月14日	合格	
261	GX-B1423/20-Y-223547	2023年1月14日	合格	
262	GX-B1423/20-Y-223548	2023年1月14日	合格	




263	GX-B1423/20-Y-223549	2023年1月14日	合格	
264	GX-B1423/20-Y-223550	2023年1月14日	合格	
265	GX-B1423/20-Y-223551	2023年1月14日	合格	
266	GX-B1423/20-Y-223552	2023年1月14日	合格	

267	GX-B1423/20-Y-223553	2023年1月14日	合格	
268	GX-B1423/20-Y-223554	2023年1月14日	合格	
269	GX-B1423/20-Y-223555	2023年1月14日	合格	
270	GX-B1423/20-Y-223556	2023年1月14日	合格	

271	GX-B1423/20-Y-223557	2023年1月14日	合格	
272	GX-B1423/20-Y-223558	2023年1月14日	合格	
273	GX-B1423/20-Y-223559	2023年1月14日	合格	
274	GX-B1423/20-Y-223560	2023年1月14日	合格	

275	GX-B1423/20-Y-223561	2023年1月14日	合格	
276	GX-B1423/20-Y-223562	2023年1月14日	合格	
277	GX-B1423/20-Y-223563	2023年1月14日	合格	
278	GX-B1423/20-Y-223564	2023年1月14日	合格	

279	GX-B1423/20-Y-223565	2023年1月14日	合格	
280	GX-B1423/20-Y-223566	2023年1月14日	合格	
281	GX-B1423/20-Y-223567	2023年1月14日	合格	
282	GX-B1423/20-Y-223568	2023年1月14日	合格	

283	GX-B1423/20-Y-223569	2023年1月14日	合格	
284	GX-B1423/20-Y-223570	2023年1月14日	合格	
285	GX-B1423/20-Y-223571	2023年1月14日	合格	
286	GX-B1423/20-Y-223572	2023年1月14日	合格	

287	GX-B1423/20-Y-223573	2023年1月14日	合格	
288	GX-B1423/20-Y-223574	2023年1月14日	合格	
289	GX-B1423/20-Y-223575	2023年1月14日	合格	
290	GX-B1423/20-Y-223576	2023年1月14日	合格	

291	GX-B1423/20-Y-223577	2023年1月14日	合格	
292	GX-B1423/20-Y-223578	2023年1月14日	合格	
293	GX-B1423/20-Y-223579	2023年1月14日	合格	
294	GX-B1423/20-Y-223580	2023年1月14日	合格	





295	GX-B1423/20-Y-223581	2023年1月14日	合格	
296	GX-B1423/20-Y-223582	2023年1月14日	合格	
297	GX-B1521/20-Y-22305	2023年1月14日	所检项目合格	
298	GX-B1521/20-Y-22306	2023年1月14日	所检项目合格	

299	GX-B1521/20-Y-22307	2023年1月14日	所检项目合格	
300	GX-B1521/20-Y-22308	2023年1月14日	所检项目合格	
301	GX-B1521/20-Y-22309	2023年1月14日	所检项目合格	
302	GX-B1521/20-Y-22310	2023年1月14日	所检项目合格	

303	GX-B1521/20-Y-22311	2023年1月14日	所检项目合格	
304	GX-B1521/20-Y-22312	2023年1月14日	所检项目合格	
305	GX-B1521/20-Y-22313	2023年1月14日	所检项目合格	
306	GX-B1521/20-Y-22314	2023年1月14日	所检项目合格	

307	GX-B1521/20-Y-22315	2023年1月14日	所检项目合格	
308	GX-B1521/20-Y-22316	2023年1月14日	所检项目合格	
309	GX-B1521/20-Y-22317	2023年1月14日	所检项目合格	
310	GX-B1521/20-Y-22318	2023年1月14日	所检项目合格	

311	GX-B1521/20-Y-22319	2023年1月14日	所检项目合格	
312	GX-B1539/22-Y-22211	2023年1月14日	所检项目合格	
313	GX-B1539/22-Y-22212	2023年1月14日	所检项目合格	
314	GX-B1539/22-Y-22213	2023年1月14日	所检项目合格	

315	GX-B1539/22-Y-22214	2023年1月14日	所检项目合格	
316	GX-B1539/22-Y-22215	2023年1月14日	所检项目合格	
317	GX-B1539/22-Y-22216	2023年1月14日	所检项目合格	
318	GX-B1539/22-Y-22217	2023年1月14日	所检项目合格	

319	GX-B1539/22-Y-22218	2023年1月14日	所检项目合格	
320	GX-B1539/22-Y-22219	2023年1月14日	所检项目合格	
321	GX-B1423/20-Y-223512	2023年1月14日	合格	
322	GX-B1423/20-Y-223513	2023年1月14日	合格	

323	GX-B1423/20-Y-223514	2023年1月14日	合格	 A yellow truck is parked on a snowy surface. Two workers in orange safety vests and dark jackets are standing in front of the truck, one on the left and one on the right. The truck has a red flag on its roof. The background shows a clear blue sky and some distant structures.
324	GX-B1423/20-Y-223515	2023年1月14日	合格	 A yellow truck is parked on a snowy surface. Two workers in orange safety vests and dark jackets are standing in front of the truck, one on the left and one on the right. The truck has a red flag on its roof. The background shows a clear blue sky and some distant structures.
325	GX-B1423/20-Y-223516	2023年1月14日	合格	 A yellow truck is parked on a snowy surface. Two workers in orange safety vests and dark jackets are standing in front of the truck, one on the left and one on the right. The truck has a red flag on its roof. The background shows a clear blue sky and some distant structures.
326	GX-B1423/20-Y-223517	2023年1月14日	合格	 A yellow truck is parked on a snowy surface. Two workers in orange safety vests and dark jackets are standing in front of the truck, one on the left and one on the right. The truck has a red flag on its roof. The background shows a clear blue sky and some distant structures.

327	GX-B1423/20-Y-223543	2023年1月14日	合格	
328	GX-B1423/20-Y-223544	2023年1月14日	合格	
329	GX-B1423/20-Y-223545	2023年1月14日	合格	
330	GX-B1423/20-Y-223546	2023年1月14日	合格	

331	GX-B1423/20-Y-223547	2023年1月14日	合格	
332	GX-B1423/20-Y-223548	2023年1月14日	合格	
333	GX-B1423/20-Y-223549	2023年1月14日	合格	
334	GX-B1423/20-Y-223550	2023年1月14日	合格	

335	GX-B1423/20-Y-223551	2023年1月14日	合格	
336	GX-B1423/20-Y-223552	2023年1月14日	合格	
337	GX-B1423/20-Y-223553	2023年1月14日	合格	
338	GX-B1423/20-Y-223554	2023年1月14日	合格	


339	GX-B1423/20-Y-223555	2023年1月14日	合格	 A green dump truck is parked on a dirt surface. Two workers in orange safety vests and hard hats are standing next to it. The truck has a license plate that reads "桂B 1423". A yellow timestamp "2023/1/14" is visible in the bottom right corner of the image.
340	GX-B1423/20-Y-223556	2023年1月14日	合格	 A green dump truck is parked on a dirt surface. Two workers in orange safety vests and hard hats are standing next to it. The truck has a license plate that reads "桂B 1423". A yellow timestamp "2023/1/14" is visible in the bottom right corner of the image.
341	GX-B1423/20-Y-223557	2023年1月14日	合格	 A green dump truck is parked on a dirt surface. Two workers in orange safety vests and hard hats are standing next to it. The truck has a license plate that reads "桂B 1423". A yellow timestamp "2023/1/14" is visible in the bottom right corner of the image.
342	GX-B1423/20-Y-223558	2023年1月14日	合格	 A green dump truck is parked on a dirt surface. Two workers in orange safety vests and hard hats are standing next to it. The truck has a license plate that reads "桂B 1423". A yellow timestamp "2023/1/14" is visible in the bottom right corner of the image.





343	GX-B1423/20-Y-223559	2023年1月14日	合格	 A green truck with the number 702 on its side. Two workers in orange safety vests are standing in front of the truck. The date 2023/12/17 is visible in the bottom right corner of the photo.
344	GX-B1423/20-Y-223560	2023年1月14日	合格	 A green truck with the number 700 on its side. Two workers in orange safety vests are standing in front of the truck. The date 2023/12/17 is visible in the bottom right corner of the photo.
345	GX-B1423/20-Y-223561	2023年1月14日	合格	 A green truck with the number 705 on its side. Two workers in orange safety vests are standing in front of the truck. The date 2023/12/17 is visible in the bottom right corner of the photo.
346	GX-B1423/20-Y-223562	2023年1月14日	合格	 A green truck with the number 703 on its side. Two workers in orange safety vests are standing in front of the truck. The date 2023/12/17 is visible in the bottom right corner of the photo.

347	GX-B1423/20-Y-223563	2023年1月14日	合格	
348	GX-B1423/20-Y-223564	2023年1月14日	合格	
349	GX-B1423/20-Y-223565	2023年1月14日	合格	
350	GX-B1423/20-Y-223566	2023年1月14日	合格	

351	GX-B1423/20-Y-223567	2023年1月14日	合格	
352	GX-B1423/20-Y-223568	2023年1月14日	合格	
353	GX-B1423/20-Y-223569	2023年1月14日	合格	
354	GX-B1423/20-Y-223570	2023年1月14日	合格	

355	GX-B1423/20-Y-223571	2023年1月14日	合格	
356	GX-B1423/20-Y-223572	2023年1月14日	合格	
357	GX-B1423/20-Y-223573	2023年1月14日	合格	
358	GX-B1423/20-Y-223574	2023年1月14日	合格	

359	GX-B1423/20-Y-223575	2023年1月14日	合格	
360	GX-B1423/20-Y-223576	2023年1月14日	合格	
361	GX-B1423/20-Y-223577	2023年1月14日	合格	
362	GX-B1423/20-Y-223578	2023年1月14日	合格	

363	GX-B1423/20-Y-223579	2023年1月14日	合格	
364	GX-B1423/20-Y-223580	2023年1月14日	合格	
365	GX-B1423/20-Y-223581	2023年1月14日	合格	
366	GX-B1423/20-Y-223582	2023年1月14日	合格	

367	GX-B1521/20-Y-22305	2023年1月14日	所检项目合格	 A yellow excavator is shown in an outdoor construction setting. The machine is positioned on a dirt surface, and its arm is partially visible. A person is standing near the base of the excavator. The background shows a clear sky and some distant structures. A yellow timestamp '2023-12-26' is visible in the bottom right corner of the image.
368	GX-B1521/20-Y-22306	2023年1月14日	所检项目合格	 A yellow excavator is shown in an outdoor construction setting. The machine is positioned on a dirt surface, and its arm is partially visible. A person is standing near the base of the excavator. The background shows a clear sky and some distant structures. A yellow timestamp '2023-12-26' is visible in the bottom right corner of the image.
369	GX-B1521/20-Y-22307	2023年1月14日	所检项目合格	 A yellow excavator is shown in an outdoor construction setting. The machine is positioned on a dirt surface, and its arm is partially visible. A person is standing near the base of the excavator. The background shows a clear sky and some distant structures. A yellow timestamp '2023-12-27' is visible in the bottom right corner of the image.
370	GX-B1521/20-Y-22308	2023年1月14日	所检项目合格	 A yellow excavator is shown in an outdoor construction setting. The machine is positioned on a dirt surface, and its arm is partially visible. A person is standing near the base of the excavator. The background shows a clear sky and some distant structures. A yellow timestamp '2023-12-27' is visible in the bottom right corner of the image.

371	GX-B1521/20-Y-22309	2023年1月14日	所检项目合格	 A yellow excavator is shown at a construction site, positioned on a dirt surface. The background shows a clear sky and some distant structures. A yellow timestamp '2022/12/27' is visible in the bottom right corner of the image.
372	GX-B1521/20-Y-22310	2023年1月14日	所检项目合格	 A yellow excavator is working on a pile of rubble and debris. The excavator's arm is extended, and it appears to be in the process of moving or breaking up the material. A yellow timestamp '2022/12/27' is visible in the bottom right corner of the image.
373	GX-B1521/20-Y-22311	2023年1月14日	所检项目合格	 A yellow excavator is shown at a construction site, positioned on a dirt surface. The background shows a clear sky and some distant structures. A yellow timestamp '2022/12/27' is visible in the bottom right corner of the image.
374	GX-B1521/20-Y-22312	2023年1月14日	所检项目合格	 A yellow excavator is working on a pile of rubble and debris. The excavator's arm is extended, and it appears to be in the process of moving or breaking up the material. A yellow timestamp '2022/12/27' is visible in the bottom right corner of the image.

375	GX-B1521/20-Y-22313	2023年1月14日	所检项目合格	
376	GX-B1521/20-Y-22314	2023年1月14日	所检项目合格	
377	GX-B1521/20-Y-22315	2023年1月14日	所检项目合格	
378	GX-B1521/20-Y-22316	2023年1月14日	所检项目合格	

379	GX-B1521/20-Y-22317	2023年1月14日	所检项目合格	 A yellow excavator with 'L150' and 'LCM5' markings is shown in an outdoor setting. A date stamp '2022/12/27' is visible in the bottom right corner.
380	GX-B1521/20-Y-22318	2023年1月14日	所检项目合格	 A yellow excavator with 'L150' and 'LCM5' markings is shown in an outdoor setting. A date stamp '2022/12/27' is visible in the bottom right corner.
381	GX-B1521/20-Y-22319	2023年1月14日	所检项目合格	 A yellow excavator with 'L150' and 'LCM5' markings is shown in an outdoor setting. A date stamp '2022/12/27' is visible in the bottom right corner.
382	GX-B1539/22-Y-22211	2023年1月14日	所检项目合格	 A yellow wheel loader with 'L150' and 'LCM5' markings is shown in an outdoor setting. A date stamp '2022/12/27' is visible in the bottom right corner.

383	GX-B1539/22-Y-22212	2023年1月14日	所检项目合格	 A yellow wheel loader is parked on a paved surface. Two workers in safety gear are standing next to it. The photo has a timestamp of 2022/12/09.
384	GX-B1539/22-Y-22213	2023年1月14日	所检项目合格	 A yellow wheel loader is parked on a paved surface. Two workers in safety gear are standing next to it. The photo has a timestamp of 2022/12/30.
385	GX-B1539/22-Y-22214	2023年1月14日	所检项目合格	 A yellow wheel loader is parked on a paved surface. Two workers in safety gear are standing next to it. The photo has a timestamp of 2022/12/30.
386	GX-B1539/22-Y-22215	2023年1月14日	所检项目合格	 A yellow wheel loader is parked on a paved surface. Two workers in safety gear are standing next to it. The photo has a timestamp of 2022/12/30.

387	GX-B1539/22-Y-22216	2023年1月14日	所检项目合格	
388	GX-B1539/22-Y-22217	2023年1月14日	所检项目合格	
389	GX-B1539/22-Y-22218	2023年1月14日	所检项目合格	
390	GX-B1539/22-Y-22219	2023年1月14日	所检项目合格	

391	GX-B1521/20-Y-23017	2023/1/14	所检项目合格	
392	GX-B1521/20-Y-23018	2023/1/14	所检项目合格	
393	GX-B1521/20-Y-23019	2023/1/14	所检项目合格	
394	GX-B1521/20-Y-23020	2023/1/14	所检项目合格	

395	GX-B1521/20-Y-23021	2023/1/14	所检项目合格	
396	GX-B1521/20-Y-23022	2023/1/14	所检项目合格	
397	GX-B1539/22-Y-22223	2023/1/14	所检项目合格	
398	GX-B1539/22-Y-22224	2023/1/14	所检项目合格	

399	GX-B1557/22-Y-22012	2023/1/14	所检项目合格	 A yellow wheel loader is parked on a dirt surface. Two workers in safety gear are standing near the front of the machine. The date stamp '2023/1/14' is visible in the bottom right corner of the photo.
400	GX-B1556/22-Y-22004	2023/1/14	所检项目合格	 A yellow bulldozer is parked on a dirt surface. Two workers in safety gear are standing near the front of the machine. The date stamp '2023/1/14' is visible in the bottom right corner of the photo.
401	GX-B1423/20-Y-23031	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The date stamp '2023/1/14' is visible in the bottom right corner of the photo.
402	GX-B1423/20-Y-23032	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The date stamp '2023/1/14' is visible in the bottom right corner of the photo.

403	GX-B1423/20-Y-23033	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective. The truck's bed is raised. Two workers in safety gear are standing near the front of the truck. The background is a clear blue sky and a flat, sandy ground.
404	GX-B1423/20-Y-23034	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective. The truck's bed is raised. Two workers in safety gear are standing near the front of the truck. The background is a clear blue sky and a flat, sandy ground.
405	GX-B1423/20-Y-23035	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective. The truck's bed is raised. Two workers in safety gear are standing near the front of the truck. The background is a clear blue sky and a flat, sandy ground.
406	GX-B1423/20-Y-23036	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective. The truck's bed is raised. Two workers in safety gear are standing near the front of the truck. The background is a clear blue sky and a flat, sandy ground.

407	GX-B1423/20-Y-23037	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. Two workers in safety gear are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
408	GX-B1423/20-Y-23038	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. Two workers in safety gear are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
409	GX-B1423/20-Y-23039	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. Two workers in safety gear are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
410	GX-B1423/20-Y-23040	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. Two workers in safety gear are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.

411	GX-B1423/20-Y-23041	2023/1/14	合格	
412	GX-B1423/20-Y-23042	2023/1/14	合格	
413	GX-B1423/20-Y-23043	2023/1/14	合格	
414	GX-B1423/20-Y-23044	2023/1/14	合格	

415	GX-B1423/20-Y-23045	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a sandy surface. Several people are standing around the truck. A yellow date stamp '2023/1/14' is visible in the bottom right corner of the image.
416	GX-B1423/20-Y-23046	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a sandy surface. Several people are standing around the truck. A yellow date stamp '2023/1/14' is visible in the bottom right corner of the image.
417	GX-B1423/20-Y-23047	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a sandy surface. Several people are standing around the truck. A yellow date stamp '2023/1/14' is visible in the bottom right corner of the image.
418	GX-B1423/20-Y-23048	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a sandy surface. Several people are standing around the truck. A yellow date stamp '2023/1/14' is visible in the bottom right corner of the image.

419	GX-B1423/20-Y-23049	2023/1/14	合格	
420	GX-B1423/20-Y-23050	2023/1/14	合格	
421	GX-B1423/20-Y-23051	2023/1/14	合格	
422	GX-B1423/20-Y-23052	2023/1/14	合格	

423	GX-B1423/20-Y-23053	2023/1/14	合格	
424	GX-B1423/20-Y-23054	2023/1/14	合格	
425	GX-B1423/20-Y-23055	2023/1/14	合格	
426	GX-B1423/20-Y-23056	2023/1/14	合格	

427	GX-B1423/20-Y-23057	2023/1/14	合格	
428	GX-B1423/20-Y-23058	2023/1/14	合格	
429	GX-B1423/20-Y-23059	2023/1/14	合格	
430	GX-B1423/20-Y-23060	2023/1/14	合格	

431	GX-B1423/20-Y-23061	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. Two people are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023-1-14' is visible in the bottom right corner of the image.
432	GX-B1423/20-Y-23062	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. Two people are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023-1-14' is visible in the bottom right corner of the image.
433	GX-B1423/20-Y-23063	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. Two people are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023-1-14' is visible in the bottom right corner of the image.
434	GX-B1423/20-Y-23064	2023/1/14	合格	 A yellow dump truck is parked on a sandy surface. Two people are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023-1-14' is visible in the bottom right corner of the image.

435	GX-B1423/20-Y-23065	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a dirt surface. Two workers in high-visibility vests are standing near the front. A date stamp '2023-1-9' is visible in the bottom right corner.
436	GX-B1423/20-Y-23066	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a dirt surface. Two workers in high-visibility vests are standing near the front. A date stamp '2023-1-9' is visible in the bottom right corner.
437	GX-B1423/20-Y-23067	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a dirt surface. Two workers in high-visibility vests are standing near the front. A date stamp '2023-1-9' is visible in the bottom right corner.
438	GX-B1423/20-Y-23068	2023/1/14	合格	 A yellow dump truck with its bed raised, parked on a dirt surface. Two workers in high-visibility vests are standing near the front. A date stamp '2023-1-9' is visible in the bottom right corner.

439	GX-B1423/20-Y-23069	2023/1/14	合格	 A yellow dump truck is parked on a dirt road in a desert-like environment. A person is standing near the front of the truck. The date stamp in the bottom right corner of the image is 2023-1-14.
440	GX-B1423/20-Y-23070	2023/1/14	合格	 A yellow dump truck is parked on a dirt road. A person is standing near the front of the truck. The date stamp in the bottom right corner of the image is 2023-1-14.
441	GX-B1423/20-Y-223624	2023/1/13	合格	 A yellow truck is parked on a dirt road. A person is standing near the front of the truck. The date stamp in the bottom right corner of the image is 2023-1-13.
442	GX-B1423/20-Y-223625	2023/1/13	合格	 A yellow truck is parked on a dirt road. Two people are standing near the front of the truck. The date stamp in the bottom right corner of the image is 2023-1-13.

443	GX-B1539/22-Y-22220	2023/1/14	所检项目合格	 A yellow wheel loader is parked in a snowy field. Two people are standing next to it. The date stamp in the bottom right corner reads 2023/1/14.
444	GX-B1539/22-Y-22221	2023/1/14	所检项目合格	 A yellow wheel loader is parked in a snowy field. Two people are standing next to it. The date stamp in the bottom right corner reads 2023/1/14.
445	GX-B1539/22-Y-22222	2023/1/14	所检项目合格	 A yellow wheel loader is parked in a snowy field. Two people are standing next to it. The date stamp in the bottom right corner reads 2023/1/14.
446	GX-B1521/20-Y-22332	2023/1/14	所检项目合格	 A yellow tracked loader is parked in a snowy field. Two people are standing next to it. The date stamp in the bottom right corner reads 2023/1/14.

447	GX-B1521/20-Y-22333	2023/1/14	所检项目合格	
448	GX-B1521/20-Y-22334	2023/1/14	所检项目合格	
449	GX-B1521/20-Y-22335	2023/1/14	所检项目合格	
450	GX-B1521/20-Y-22336	2023/1/14	所检项目合格	

451	GX-B1557/22-Y-22011	2023/1/14	所检项目合格	
452	GX-B1423/20-Y-223583	2023/1/14	合格	
453	GX-B1423/20-Y-223584	2023/1/14	合格	
454	GX-B1423/20-Y-223585	2023/1/14	合格	

455	GX-B1423/20-Y-223586	2023/1/14	合格	 A yellow dump truck with the number 320 on its side, parked on a dirt surface. Two people are standing near the front of the truck. A yellow timestamp '2022-12-19' is visible in the bottom right corner of the image.
456	GX-B1423/20-Y-223587	2023/1/14	合格	 A yellow dump truck with the number 321 on its side, parked on a dirt surface. Two people are standing near the front of the truck. A yellow timestamp '2022-12-19' is visible in the bottom right corner of the image.
457	GX-B1423/20-Y-223588	2023/1/14	合格	 A yellow dump truck with the number 322 on its side, parked on a dirt surface. Two people are standing near the front of the truck. A yellow timestamp '2022-12-19' is visible in the bottom right corner of the image.
458	GX-B1423/20-Y-223589	2023/1/14	合格	 A yellow dump truck with the number 323 on its side, parked on a dirt surface. Two people are standing near the front of the truck. A yellow timestamp '2022-12-19' is visible in the bottom right corner of the image.

459	GX-B1423/20-Y-223590	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The date '2022-12-19' is visible in the bottom right corner of the image.
460	GX-B1423/20-Y-223591	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The date '2022-12-19' is visible in the bottom right corner of the image.
461	GX-B1423/20-Y-223592	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The date '2022-12-19' is visible in the bottom right corner of the image.
462	GX-B1423/20-Y-223593	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front of the truck. The date '2022-12-19' is visible in the bottom right corner of the image.

463	GX-B1423/20-Y-223594	2023/1/14	合格	
464	GX-B1423/20-Y-223595	2023/1/14	合格	
465	GX-B1423/20-Y-223623	2023/1/14	合格	
466	GX-B1423/20-Y-223596	2023/1/14	合格	





467	GX-B1423/20-Y-223597	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective, parked on a dirt surface. The truck's bed is slightly raised. A person is standing near the front wheel. The background is a clear blue sky. A yellow timestamp '2022/12/20' is visible in the bottom right corner of the image.
468	GX-B1423/20-Y-223598	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective, parked on a dirt surface. The truck's bed is slightly raised. A person is standing near the front wheel. The background is a clear blue sky. A yellow timestamp '2022/12/20' is visible in the bottom right corner of the image.
469	GX-B1423/20-Y-223599	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective, parked on a dirt surface. The truck's bed is slightly raised. A person is standing near the front wheel. The background is a clear blue sky. A yellow timestamp '2022/12/20' is visible in the bottom right corner of the image.
470	GX-B1423/20-Y-223600	2023/1/14	合格	 A yellow dump truck is shown from a side-rear perspective, parked on a dirt surface. The truck's bed is slightly raised. A person is standing near the front wheel. The background is a clear blue sky. A yellow timestamp '2022/12/20' is visible in the bottom right corner of the image.



471	GX-B1423/20-Y-223601	2023/1/14	合格	
472	GX-B1423/20-Y-223602	2023/1/14	合格	
473	GX-B1423/20-Y-223603	2023/1/14	合格	
474	GX-B1423/20-Y-223604	2023/1/14	合格	

475	GX-B1423/20-Y-223605	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. A person is standing near the front of the truck. A yellow timestamp '2022/12/20' is visible in the bottom right corner of the photo.
476	GX-B1423/20-Y-223606	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. The scene is backlit by a bright sun, creating a lens flare effect. A person is standing near the front of the truck. A yellow timestamp '2022/12/20' is visible in the bottom right corner of the photo.
477	GX-B1423/20-Y-223607	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface. A person is standing to the left of the truck, facing it. A yellow timestamp '2022/12/20' is visible in the bottom right corner of the photo.
478	GX-B1423/20-Y-223608	2023/1/14	合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. A person is standing near the front of the truck. A yellow timestamp '2022/12/20' is visible in the bottom right corner of the photo.

479	GX-B1423/20-Y-223609	2023/1/13	合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. A person is standing near the front of the truck. A yellow timestamp '2023/1/13' is visible in the bottom right corner of the image.
480	GX-B1423/20-Y-223610	2023/1/13	合格	 A yellow dump truck is parked on a dirt surface. The sun is low in the sky, creating a bright glare. A person is standing near the front of the truck. A yellow timestamp '2023/12/21' is visible in the bottom right corner of the image.
481	GX-B1423/20-Y-223611	2023/1/13	合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. A person is standing near the front of the truck. A yellow timestamp '2023/12/21' is visible in the bottom right corner of the image.
482	GX-B1423/20-Y-223612	2023/1/13	合格	 A yellow dump truck is parked on a dirt surface. The sun is low in the sky, creating a bright glare. A person is standing near the front of the truck. A yellow timestamp '2023/12/21' is visible in the bottom right corner of the image.

483	GX-B1423/20-Y-223613	2023/1/13	合格	 A yellow dump truck is parked on a flat, sandy surface under a clear blue sky. Two people are standing near the front of the truck. A yellow timestamp '2022/12/21' is visible in the bottom right corner of the image.
484	GX-B1423/20-Y-223614	2023/1/13	合格	 A yellow dump truck is parked on a flat, sandy surface. A person is standing near the front of the truck. A yellow timestamp '2022/12/21' is visible in the bottom right corner of the image.
485	GX-B1423/20-Y-223615	2023/1/13	合格	 A yellow dump truck is parked on a flat, sandy surface. Two people are standing near the front of the truck. A yellow timestamp '2022/12/21' is visible in the bottom right corner of the image.
486	GX-B1423/20-Y-223616	2023/1/13	合格	 A yellow dump truck is parked on a flat, sandy surface. A person is standing near the front of the truck. A yellow timestamp '2022/12/21' is visible in the bottom right corner of the image.

487	GX-B1423/20-Y-223617	2023/1/13	合格	 A yellow dump truck is parked on a flat, sandy surface. A person is standing near the front of the truck, and another person is kneeling on the ground in front of the truck. The truck's bed is raised. A yellow timestamp '2022/12/21' is visible in the bottom right corner of the photo.
488	GX-B1423/20-Y-223618	2023/1/13	合格	 A yellow dump truck is parked on a flat, sandy surface. A person is standing near the front of the truck, and another person is kneeling on the ground in front of the truck. The truck's bed is raised. A yellow timestamp '2022/12/21' is visible in the bottom right corner of the photo.
489	GX-B1423/20-Y-223619	2023/1/13	合格	 A yellow dump truck is parked on a flat, sandy surface. A person is standing near the front of the truck, and another person is kneeling on the ground in front of the truck. The truck's bed is raised. A yellow timestamp '2022/12/21' is visible in the bottom right corner of the photo.
490	GX-B1423/20-Y-223620	2023/1/13	合格	 A yellow dump truck is parked on a flat, sandy surface. A person is standing near the front of the truck, and another person is kneeling on the ground in front of the truck. The truck's bed is raised. A yellow timestamp '2022/12/21' is visible in the bottom right corner of the photo.

491	GX-B1423/20-Y-223621	2023/1/13	合格	 A yellow dump truck is parked on a dirt surface. The truck is viewed from a front-three-quarter angle. A person is standing near the front of the truck. The date '2022/12/21' is visible in the bottom right corner of the image.
492	GX-B1423/20-Y-223622	2023/1/13	合格	 A yellow dump truck is parked on a dirt surface. The truck is viewed from a front-three-quarter angle. A person is standing near the front of the truck. The date '2022/12/21' is visible in the bottom right corner of the image.