







序号	报告编号	发布日期	结论	影像资料
264	GX-B1329/21-4-23050-23056	2023. 5. 28	本次共检氧化锌避雷器7组，7组氧化锌避雷器所检项目合格	
265	GX-B1495/20-4-231519-231529	2023. 5. 28	本次共检高压开关柜11面，11面高压开关柜所检项目合格	

266	GX-B1329/21-4-23074-23090	2023. 5. 28	本次共检氧化锌避雷器17组，17组氧化锌避雷器所检项目合格	
267	GX-B1495/20-4-231530-231544	2023. 5. 28	本次共检高压开关柜15面，15面高压开关柜所检项目合格	
268	GX-B1495/20-4-23916~23926	2023. 5. 28	本次共检高压开关柜11面，11面高压开关柜所检项目合格。	




269	GX-B1495/20-4-23927~23937	2023. 5. 28	本次共检高压开关柜11面，11面高压开关柜所检项目合格。			
270	GX-B1495/20-4-23938~23955	2023. 5. 28	本次共检高压开关柜18面，18面高压开关柜所检项目合格。			
271	GX-B1495/20-4-23956~23959	2023. 5. 28	本次共检高压开关柜4面，4台高压开关柜所检项目合格。			




272	GX-B1495/20-4-23960~23966	2023. 5. 28	本次共检高压开关柜7面，7面高压开关柜所检项目合格。	
273	GX-B1495/20-4-23967~23970	2023. 5. 28	本次共检高压防爆开关4台，4台高压防爆开关所检项目合格。	
274	GX-B1495/20-4-23971~23975	2023. 5. 28	本次共检高压防爆开关5台，5台高压防爆开关所检项目合格。	

275	GX-B1495/20-4-23976~23986	2023. 5. 28	本次共检高压开关柜11面，11面高压开关柜所检项目合格。			
276	GX-B1495/20-4-23987~231007	2023. 5. 28	本次共检高压开关柜21面，21面高压开关柜所检项目合格。			
277	GX-B1495/20-4-231008~231016	2023. 5. 28	本次共检高压开关柜9面，9面高压开关柜所检项目合格。			

278	GX-B1495/20-4-231017~231024	2023. 5. 28	本次共检高压开关柜8面，8面高压开关柜所检项目合格。	
279	GX-B1495/20-4-231025~231032	2023. 5. 28	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	
280	GX-B1495/20-4-231033~231042	2023. 5. 28	本次共检高压开关柜10面，10面高压开关柜所检项目合格。	




281	GX-B1495/20-4-231043~231054	2023. 5. 28	本次共检高压开关柜12面，12面高压开关柜所检项目合格。	
282	GX-B1495/20-4-231055~231064	2023. 5. 28	本次共检高压开关柜10面，10面高压开关柜所检项目合格。	
283	GX-B1495/20-4-231065~231086	2023. 5. 28	本次共检高压防爆开关22台，22台高压防爆开关所检项目合格。	




284	GX-B1495/20-4-231087~231096	2023. 5. 28	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	 <p style="text-align: right; color: orange;">2023. 3. 31</p>
285	GX-B1495/20-4-231097~231120	2023. 5. 28	本次共检高压防爆开关24台，24台高压防爆开关所检项目合格。	 <p style="text-align: right; color: orange;">2023. 4. 1</p>
286	GX-B1495/20-4-231121~231140	2023. 5. 28	次共检高压防爆开关20台，20台高压防爆开关所检项目合格。	 <p style="text-align: right; color: orange;">2023. 4. 3</p>



287	GX-B1495/20-4-231141~231161	2023. 5. 28	本次共检高压防爆开关21台，21台高压防爆开关所检项目合格。	
288	GX-B1495/20-4-231162~231189	2023. 5. 28	本次共检高压防爆开关28台，28台高压防爆开关所检项目合格。	
289	GX-B1495/20-4-231190~231195	2023. 5. 28	本次共检高压防爆开关6台，6台高压防爆开关所检项目合格。	

290	GX-B1495/20-4-231196~231219	2023. 5. 28	本次共检高压防爆开关24台，24台高压防爆开关所检项目合格。	
291	GX-B1495/20-4-231220~231243	2023. 5. 28	本次共检高压防爆开关24台，24台高压防爆开关所检项目合格。	
292	GX-B1495/20-4-231244~231265	2023. 5. 28	本次共检高压防爆开关22台，22台高压防爆开关所检项目合格。	

293	GX-B1495/20-4-231266~231296	2023. 5. 28	本次共检高压防爆开关31台，31台高压防爆开关所检项目合格。	
294	GX-B1495/20-4-231297~231329	2023. 5. 28	本次共检高压防爆开关33台，33台高压防爆开关所检项目合格。	
295	GX-B1495/20-4-231330~231356	2023. 5. 28	本次共检高压防爆开关27台，27台高压防爆开关所检项目合格。	




296	GX-B1495/20-4-231357~231386	2023. 5. 28	本次共检高压防爆开关30台，30台高压防爆开关所检项目合格。	
297	GX-B1495/20-4-231387~231391	2023. 5. 28	本次共检高压防爆开关5台，5台高压防爆开关所检项目合格。	
298	GX-B1321/20-4-23790-23797	2023. 5. 28	本次共检电力电缆8条，8条电力电缆所检项目合格	


299	GX-B1321/20-4-23785-23789	2023. 5. 28	本次共检电力电缆5条，5条电力电缆所检项目合格	
300	GX-B1323/21-4-23273~23278	2023. 5. 28	本次共检三相交流电动机6台，6台三相交流电动机所检项目合格。	
301	GX-B1323/21-4-23279~23290	2023. 5. 28	本次共检三相交流电动机12台，12台三相交流电动机所检项目合格。	

302	GX-B1323/21-4-23291~23297	2023. 5. 28	<p>本次共检三相交流电动机7台，7台三相交流电动机所检项目合格。</p>		
303	GX-B1323/21-4-23298~23301	2023. 5. 28	<p>本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。</p>		
304	GX-B1323/21-4-23302~23303	2023. 5. 28	<p>本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。</p>		

305	GX-B1323/21-4-23143~23153	2023. 5. 28	本次共检三相交流电动机11台，11台三相交流电动机所检项目合格。	
306	GX-B1323/21-4-23154	2023. 5. 28	本次共检三相交流电动机1台，1台三相交流电动机所检项目合格。	
307	GX-B1323/21-4-23155	2023. 5. 28	本次共检三相交流电动机1台，1台三相交流电动机所检项目合格。	




308	GX-B1323/21-4-23156~23157	2023. 5. 28	本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。 。	
309	GX-B1323/21-4-23158~23165	2023. 5. 28	本次共检三相交流电动机8台，8台三相交流电动机所检项目合格。 。	
310	GX-B1323/21-4-23166~23167	2023. 5. 28	本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。 。	

311	GX-B1323/21-4-23168~23173	2023. 5. 28	<p>本次共检三相交流电动机6台，6台三相交流电动机所检项目合格。</p>			
312	GX-B1323/21-4-23174~23179	2023. 5. 28	<p>本次共检三相交流电动机6台，6台三相交流电动机所检项目合格。</p>			
313	GX-B1323/21-4-23180~23189	2023. 5. 28	<p>本次共检三相交流电动机10台，10台三相交流电动机所检项目合格。</p>			

314	GX-B1323/21-4-23190~23196	2023. 5. 28	本次共检三相交流电动机7台，7台三相交流电动机所检项目合格。 。	
315	GX-B1323/21-4-23197~23200	2023. 5. 28	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。 。	
316	GX-B1323/21-4-23201~23203	2023. 5. 28	本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。 。	

317	GX-B1323/21-4-23204~23210	2023. 5. 28	<p>本次共检三相交流电动机7台，7台三相交流电动机所检项目合格。</p>	
318	GX-B1323/21-4-23211~23216	2023. 5. 28	<p>本次共检三相交流电动机6台，6台三相交流电动机所检项目合格。</p>	
319	GX-B1323/21-4-23217~23219	2023. 5. 28	<p>本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。</p>	

320	GX-B1323/21-4-23220~23223	2023. 5. 28	<p>本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。</p>	
321	GX-B1323/21-4-23224~23227	2023. 5. 28	<p>本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。</p>	
322	GX-B1323/21-4-23228~23234	2023. 5. 28	<p>本次共检三相交流电动机7台，7台三相交流电动机所检项目合格。</p>	




323	GX-B1323/21-4-23235~23242	2023. 5. 28	<p>本次共检三相交流电动机8台，8台三相交流电动机所检项目合格。</p> <p>。</p>	
324	GX-B1323/21-4-23243~23245	2023. 5. 28	<p>本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。</p> <p>。</p>	
325	GX-B1323/21-4-23252~23257	2023. 5. 29	<p>本次共检三相交流电动机6台，6台三相交流电动机所检项目合格。</p>	



326	GX-B1329/21-4-23057~23073	2023. 5. 29	<p>本次共检氧化锌避雷器17组，17组氧化锌避雷器所检项目合格。</p>	
327	GX-B1310/21-4-23062	2023. 5. 29	符合标准要求	
328	GX-B1310/21-4-23058	2023. 5. 29	符合标准要求	

329	GX-B1350/21-4-23057	2023. 5. 29	本次共检验接地装置5处，5处所检项目合格。	
330	GX-B1350/21-4-23058	2023. 5. 29	本次共检验接地装置6处，6处所检项目合格。	
331	GX-B1350/21-4-23059	2023. 5. 29	本次共检验接地装置8处，8处所检项目合格。	



332	GX-B1350/21-4-23060	2023. 5. 29	本次共检验接地装置12处，12处接地装置所检项目合格。	
333	GX-B1350/21-4-23040	2023. 5. 29	所检项目合格。	
334	GX-B1350/21-4-23041	2023. 5. 29	所检项目合格。	

335	GX-B1350/21-4-23042	2023. 5. 29	所检项目合格。	
336	GX-B1350/21-4-23043	2023. 5. 29	所检项目合格。	
337	GX-B1350/21-4-23044	2023. 5. 29	所检项目合格。	

338	GX-B1350/21-4-23045	2023. 5. 29	所检项目合格。	 <p>2023. 4. 6</p>
339	GX-B1350/21-4-23046	2023. 5. 29	所检项目合格。	 <p>2023. 4. 7</p>
340	GX-B1350/21-4-23047	2023. 5. 29	本次共检验接地装置2处，2处所检项目合格。	 <p>2023. 4. 9</p>




341	GX-B1350/21-4-23048	2023. 5. 29	所检项目合格。	 <p>2023. 4. 10</p>
342	GX-B1350/21-4-23049	2023. 5. 29	本次共检验接地装置2处，2处所检项目合格。	 <p>2023. 4. 11</p>
343	GX-B1350/21-4-23050	2023. 5. 29	所检项目合格。	 <p>2023. 4. 12</p>

344	GX-B1350/21-4-23051	2023. 5. 29	所检项目合格。	
345	GX-B1350/21-4-23052	2023. 5. 29	所检项目合格。	
346	GX-B1312/20-4-23475-23476	2023. 5. 30	本次共检电力变压器2台，2台电力变压器所检项目合格	




347	GX-B1312/20-4-23477-23479	2023. 5. 30	本次共检电力变压器3台，3台电力变压器所检项目合格	
348	GX-B1329/21-4-23095~23101	2023. 5. 30	本次共检氧化锌避雷器7组，7组氧化锌避雷器所检项目合格。	
349	GX-B1329/21-4-23102~23110	2023. 5. 30	本次共检氧化锌避雷器9组，9组氧化锌避雷器所检项目合格。	

350	GX-B1329/21-4-23111~23119	2023. 5. 30	本次共检氧化锌避雷器9组，9组氧化锌避雷器所检项目合格。			
351	GX-B1312/20-4-23753~23762	2023. 5. 30	所检项目合格			
352	GX-B1312/20-4-23763~23771	2023. 5. 30	所检项目合格			

353	GX-B1312/20-4-23773~23784	2023. 5. 30	所检项目合格		 <p>2023. 5. 14</p>	
354	GX-B1321/20-4-23458~23463	2023. 5. 30	所检项目合格		 <p>2023. 4. 27</p>	
355	GX-B1321/20-4-23464~23465	2023. 5. 30	所检项目合格		 <p>2023. 4. 28</p>	

356	GX-B1321/20-4-23467~23471	2023. 5. 30	所检项目合格	 <p>2023. 5. 14</p>
357	GX-B1314/21-4-23020~23025	2023. 5. 30	本次共检验干式电抗器6台，6台所检项目合格。	 <p>2023/5/14</p>
358	GX-B1495/20-4-231483~231491	2023. 5. 30	本次共检高压防爆开关9台，9台高压防爆开关所检项目合格。	 <p>2023/4/28</p>

359	GX-B1495/20-4-231517~231518	2023. 5. 30	<p>本次共检高压开关柜2面，2面高压开关柜所检项目合格。</p>	 <p>A photograph showing two high-voltage switchgear cabinets in a room. A person is visible in the background, and the date '2023/4/30' is printed in the bottom right corner of the image.</p>
360	GX-B1495/20-4-231509~231516	2023. 5. 30	<p>本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。</p>	 <p>A photograph taken in a dark environment showing a person inspecting high-voltage explosion-proof switches. The person is wearing a reflective safety vest. The date '2023/4/30' is printed in the bottom right corner of the image.</p>
361	GX-B1495/20-4-231492~231508	2023. 5. 30	<p>本次共检高压开关柜17面，高压开关柜17面所检项目合格。</p>	 <p>A photograph showing a person inspecting high-voltage switchgear cabinets in a room. The date '2023/4/29' is printed in the bottom right corner of the image.</p>

362	GX-B1323/21-4-23262~23265	2023. 5. 30	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。	
363	GX-B1323/21-4-23266~23272	2023. 5. 30	本次共检三相交流电动机6台，6台三相交流电动机所检项目合格。	
364	GX-B1312/20-4-23472-23474	2023. 5. 30	本次共检电力变压器3台，3台所检项目合格	

365	GX-B1495/20-4-231764-231765	2023. 5. 30	本次共检电压互感器2台，2台电压互感器所检项目合格	
366	GX-B1495/20-4-231776-231805	2023. 5. 30	本次共检电流互感器30台，30台电流互感器所检项目合格	
367	GX-B1312/20-4-23350~23356	2023. 5. 30	本次共检电力变压器7台，7台所检项目合格。	

368	GX-B1312/20-4-23357~23358	2023. 5. 30	本次共检电力变压器2台，2台所检项目合格。	
369	GX-B1312/20-4-23359~23363	2023. 5. 30	本次共检电力变压器5台，5台所检项目合格。	
370	GX-B1312/20-4-23364~23365	2023. 5. 30	本次共检电力变压器2台，2台所检项目合格。	




371	GX-B1312/20-4-23366	2023. 5. 30	所检项目合格。	
372	GX-B1312/20-4-23367~23371	2023. 5. 30	本次共检电力变压器5台，5台所检项目合格。	
373	GX-B1312/20-4-23372~23375	2023. 5. 30	本次共检电力变压器4台，4台所检项目合格。	


374	GX-B1312/20-4-23376~23378	2023. 5. 30	本次共检电力变压器3台，3台所检项目合格。		
375	GX-B1312/20-4-23379	2023. 5. 30	所检项目合格。		
376	GX-B1312/20-4-23380~23384	2023. 5. 30	本次共检电力变压器5台，5台所检项目合格。		

377	GX-B1312/20-4-23385~23387	2023. 5. 30	本次共检电力变压器3台，3台所检项目合格。			
378	GX-B1312/20-4-23388~23391	2023. 5. 30	本次共检电力变压器4台，4台所检项目合格。			
379	GX-B1312/20-4-23392~23393	2023. 5. 30	本次共检电力变压器2台，2台所检项目合格。			


380	GX-B1312/20-4-23394	2023. 5. 30	所检项目合格。	
381	GX-B1312/20-4-23395~23396	2023. 5. 30	本次共检电力变压器2台，2台所检项目合格。	
382	GX-B1312/20-4-23397~23398	2023. 5. 30	本次共检电力变压器2台，2台所检项目合格。	




383	GX-B1312/20-4-23399~23402	2023. 5. 30	本次共检电力变压器4台，4台所检项目合格。	 <p>2023. 4. 4</p>
384	GX-B1312/20-4-23403	2023. 5. 30	所检项目合格。	 <p>2023. 4. 5</p>
385	GX-B1312/20-4-23404~23406	2023. 5. 30	本次共检电力变压器3台，3台所检项目合格。	 <p>2023. 4. 6</p>


386	GX-B1312/20-4-23407~23409	2023. 5. 30	本次共检电力变压器3台，3台所检项目合格。	 <p>2023. 4. 7</p>
387	GX-B1312/20-4-23410~23412	2023. 5. 30	本次共检电力变压器3台，3台所检项目合格。	 <p>2023. 4. 9</p>
388	GX-B1312/20-4-23413~23414	2023. 5. 30	本次共检电力变压器2台，2台所检项目合格。	 <p>2023. 4. 10</p>

389	GX-B1312/20-4-23415~23418	2023. 5. 30	本次共检电力变压器4台，4台所检项目合格。	 <p>2023. 4. 11</p>
390	GX-B1312/20-4-23419~23420	2023. 5. 30	本次共检电力变压器2台，2台所检项目合格。	 <p>2023. 4. 12</p>
391	GX-B1312/20-4-23421~23423	2023. 5. 30	本次共检电力变压器3台，3台所检项目合格。	 <p>2023. 4. 13</p>



392	GX-B1312/20-4-23424~23425	2023. 5. 30	本次共检电力变压器2台，2台所检项目合格。	
-----	---------------------------	-------------	-----------------------	---








2023.4.30



2023.5.3



2023.5.4





