



序号	报告编号	发布日期	结论	影像资料
108	GX-B1423/20-6-23536	2023/6/12	综合判定合格	
109	GX-B1423/20-6-23537	2023/6/12	综合判定合格	
110	GX-B1451/20-6-23517~23531	2023/6/13	所检项目合格	

111	GX-B1428/21-6-23001	2023/6/12	无缺陷迹痕显示	 A photograph showing two workers in red safety suits and helmets in a dark tunnel. One worker is in the foreground, and another is further back near a yellow railing. A warning sign with the text '当心电' is visible on the right. A timestamp '2023 05 20' is in the bottom right corner.
112	GX-B1428/21-6-23002	2023/6/12	无缺陷迹痕显示	 A close-up photograph of a worker wearing a red helmet with a headlamp and safety glasses. The worker is looking slightly to the side. A yellow railing is visible in the background. A timestamp '2023 05 20' is in the bottom right corner.
113	GX-B1428/21-6-23003	2023/6/12	无缺陷迹痕显示	 A photograph of a worker in a red safety suit and helmet in a tunnel. The worker is standing near a large circular opening in the tunnel wall. A timestamp '2023 05 20' is in the bottom right corner.

114	GX-B1495/20-6-23967~23969	2023/6/9	所检项目合格	 A photograph showing a row of white electrical control cabinets with various meters and switches. A timestamp '2023 04 28' is visible at the bottom right of the image.
115	GX-B1495/20-6-23970~23971	2023/6/9	所检项目合格	 A photograph of a worker wearing a red hard hat and a blue jacket, kneeling and working on a control panel. A timestamp '2023 04 29' is visible at the bottom right of the image.
116	GX-B1495/20-6-23972~23978	2023/6/9	所检项目合格	 A photograph taken in a dark environment, possibly underground. A worker is using a handheld device, possibly a detector or scanner, which is emitting a bright light. A timestamp '2023 04 28' is visible at the bottom right of the image.

117	GX-B1495/20-6-23979	2023/6/9	所检项目合格	
118	GX-B1495/20-6-231015~231020	2023/6/9	所检项目合格	
119	GX-B1495/20-6-231021~231026	2023/6/9	所检项目合格	

120	GX-B14595/20-6-23993~231014	2023/6/9	所检项目合格	 <p>2023_05_07</p>
121	GX-B1313/21-6-23150~23151	2023/6/13	所检项目合格	 <p>2023_05_10</p>
122	GX-B1328/20-6-23089	2023/6/13	所检项目合格	 <p>2023_05_11</p>

123	GX-B1328/20-6-23090	2023/6/13	所检项目合格			
124	GX-B1328/20-6-23091	2023/6/13	所检项目合格			
125	GX-B1328/20-6-23092	2023/6/13	所检项目合格			

126	GX-B1321/20-6-23521	2023/6/14	所检项目合格	
127	GX-B1321/20-6-23522~23532	2023/6/14	所检项目合格	
128	GX-B1312/20-6-23260~23263	2023/6/14	所检项目合格	

129	GX-B1312/20-6-23264~23265	2023/6/14	所检项目合格	
130	GX-B1520/20-6-23069	2023/6/14	综合判定合格	
131	GX-B1423/20-6-23581	2023/6/15	综合判定合格	

132	GX-B1423/20-6-23582	2023/6/15	综合判定合格		
133	GX-B1423/20-6-23583	2023/6/15	综合判定合格		
134	GX-B1423/20-6-23584	2023/6/15	综合判定合格		

135	GX-B1423/20-6-23585	2023/6/15	综合判定合格	
136	GX-B1423/20-6-23586	2023/6/15	综合判定合格	
137	GX-B1423/20-6-23492	2023/6/15	综合判定合格	

138	GX-B1423/20-6-23493	2023/6/15	综合判定合格		
139	GX-B1423/20-6-23494	2023/6/15	综合判定合格		
140	GX-B1423/20-6-23495	2023/6/15	综合判定合格		

141	GX-B1423/20-6-23496	2023/6/15	综合判定合格	 A photograph showing two men standing in front of a yellow MT95 excavator. The man on the left is wearing a light blue shirt and dark pants, and the man on the right is wearing a white shirt and dark pants. The excavator has the number '05' on its side. A date stamp '2023.05.20' is visible in the bottom right corner of the photo.
142	GX-B1423/20-6-23497	2023/6/15	综合判定合格	 A photograph showing two men standing in front of a yellow MT95 excavator. The man on the left is wearing a light blue shirt and dark pants, and the man on the right is wearing a light blue shirt and dark pants. The excavator has the number '06' on its side. A date stamp '2023.05.20' is visible in the bottom right corner of the photo.
143	GX-B1423/20-6-23498	2023/6/15	综合判定合格	 A photograph showing two men standing in front of a yellow MT95 excavator. The man on the left is wearing a light blue shirt and dark pants, and the man on the right is wearing a light blue shirt and dark pants. The excavator has the number '07' on its side. A date stamp '2023.05.20' is visible in the bottom right corner of the photo.

144	GX-B1423/20-6-23499	2023/6/15	综合判定合格		
145	GX-B1423/20-6-23500	2023/6/15	综合判定合格		
146	GX-B1423/20-6-23501	2023/6/15	综合判定合格		

147	GX-B1423/20-6-23470	2023/6/15	综合判定合格		
148	GX-B1423/20-6-23471	2023/6/15	综合判定合格		
149	GX-B1423/20-6-23472	2023/6/15	综合判定合格		

150	GX-B1423/20-6-23473	2023/6/15	综合判定合格			
151	GX-B1423/20-6-23474	2023/6/15	综合判定合格			
152	GX-B1423/20-6-23475	2023/6/15	综合判定合格			

153	GX-B1423/20-6-23476	2023/6/15	综合判定合格			
154	GX-B1423/20-6-23477	2023/6/15	综合判定合格			
155	GX-B1423/20-6-23478	2023/6/15	综合判定合格			

156	GX-B1423/20-6-23479	2023/6/15	综合判定合格		
157	GX-B1423/20-6-23480	2023/6/15	综合判定合格		
158	GX-B1423/20-6-23481	2023/6/15	综合判定合格		

159	GX-B1423/20-6-23482	2023/6/15	综合判定合格		
160	GX-B1423/20-6-23483	2023/6/15	综合判定合格		
161	GX-B1423/20-6-23484	2023/6/15	综合判定合格		

162	GX-B1423/20-6-23485	2023/6/15	综合判定合格		
163	GX-B1423/20-6-23486	2023/6/15	综合判定合格		
164	GX-B1423/20-6-23487	2023/6/15	综合判定合格		

165	GX-B1423/20-6-23488	2023/6/15	综合判定合格		
166	GX-B1423/20-6-23489	2023/6/15	综合判定合格		
167	GX-B1423/20-6-23490	2023/6/15	综合判定合格		

168	GX-B1423/20-6-23491	2023/6/15	综合判定合格	
169	GX-B1352/21-6-23388~23404	2023/6/16	所检项目合格	
170	GX-B1352/21-6-23405~23409	2023/6/16	所检项目合格	

171	GX-B1352/21-6-23410~23423	2023/6/16	所检项目合格	 <p>0000000 000000 2023/05/10 11:06:49</p>
-----	---------------------------	-----------	--------	---

