








序号	报告编号	发布日期	结论	影像资料
249	GX-B1323/21-6-23174~23178	2023/6/26	所检项目合格	 <p>A worker wearing a blue uniform, a headlamp, and orange gloves is working on a piece of equipment in a dark environment. The worker is holding a white bag and a tool. The equipment is illuminated by the worker's headlamp. The image has a timestamp 'DS1_0000000_000000 2023/05/08 10:21:10' at the bottom.</p>
250	GX-B1323/21-6-23179~23181	2023/6/26	所检项目合格	 <p>A worker wearing a dark uniform, a red helmet, and safety glasses is working on a large green cylindrical machine. The worker is kneeling and using a tool. The machine is illuminated by a light source. The image has a timestamp '2023 05 08' at the bottom.</p>
251	GX-B1323/21-6-23230~23233	2023/6/27	所检项目合格	 <p>A worker wearing a blue uniform and a cap is standing next to a large blue cylindrical machine in a well-lit area. The worker is holding a tool. The machine is mounted on a red base. The image has a timestamp '2023 05 31' at the bottom.</p>

252	GX-B1520/20-6-23057	2023/6/27	综合判定合格			
253	GX-B1520/20-6-23058	2023/6/27	综合判定合格			
254	GX-B1520/20-6-23059	2023/6/27	综合判定合格			



255	GX-B1520/20-6-23060	2023/6/27	综合判定合格	
256	GX-B1520/20-6-23061	2023/6/27	综合判定合格	
257	GX-B1520/20-6-23062	2023/6/27	综合判定合格	

258	GX-B1520/20-6-23063	2023/6/27	综合判定合格			
259	GX-B1520/20-6-23064	2023/6/27	综合判定合格			
260	GX-B1520/20-6-23065	2023/6/27	综合判定合格			

261	GX-B1300/20-6-23004	2023/6/28	综合判定合格		 2023 06 10	
262	GX-B1350/21-6-23036	2023/6/28	所检项目合格		 2023 05 31	
263	GX-B1310/21-6-23069	2023/6/28	超过 Φ 2mm当量直径		 2023 05 29	



264	GX-B1310/21-6-23070	2023/6/28	超过 Φ 2mm当量直径			
265	GX-B1310/21-6-23071	2023/6/28	超过 Φ 2mm当量直径			
266	GX-B1428/21-6-23004	2023/6/28	无缺陷迹痕显示			

267	GX-B1310/21-6-23066	2023/6/28	未发现超过 $\Phi 1\text{mm}$ 当量直径的缺陷	
268	GX-B1310/21-6-23067	2023/6/28	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	
269	GX-B1310/21-6-23068	2023/6/28	符合标准要求	

270	GX-B1359/21-6-23075~23092	2023/6/28	所检项目合格	
271	GX-B1359/21-6-23095~23105	2023/6/28	所检项目合格	
272	GX-B1359/21-6-23093~23094	2023/6/28	所检项目合格	

273	GX-B1359/21-6-23054~23059	2023/6/28	所检项目合格	 <p>2023 05 09</p>
274	GX-B1359/21-6-23060~23064	2023/6/28	所检项目合格	
275	GX-B1359/21-6-23065~23073	2023/6/28	所检项目合格	 <p>2023 05 10</p>

276	GX-B1323/21-6-23182~23187	2023/6/29	所检项目合格	
277	GX-B1323/21-6-23188~23196	2023/6/29	所检项目合格	
278	GX-B1323/21-6-23197~23198	2023/6/29	所检项目合格	

279	GX-B1323/21-6-23199~23203	2023/6/29	所检项目合格	
280	GX-B1323/21-6-23204~23209	2023/6/29	所检项目合格	
281	GX-B1323/21-6-23210~23221	2023/6/29	所检项目合格	

282	GX-B1323/21-6-23222~23229	2023/6/30	所检项目合格		
-----	---------------------------	-----------	--------	--	---