

序号	报告编号	发布日期	结论	影像资料
23	GX-B416/22-1-23023	2023/10/23	综合判定：合格。	 <p>A photograph showing a worker in a dark environment, possibly a tunnel or underground facility, using a bright flashlight to inspect equipment. The worker is wearing a safety vest and a hard hat. The scene is dimly lit, with the primary light source being the flashlight. A timestamp in the bottom right corner reads "DSJ_0000000_000000 2023/09/21 10:15:48".</p>
24	GX-B1310/21-7-23099	2023. 10. 30	符合标准要求。	 <p>A photograph showing a worker in a dark environment, wearing a red hard hat and a dark shirt, using a flashlight to inspect a yellow equipment case. The worker is standing next to the case, and the scene is dimly lit. A timestamp in the bottom right corner reads "2023. 10. 17".</p>
25	GX-B1328/20-7-23042	2023. 10. 30	本次共检绝缘手套4只，4只绝缘手套合格。	 <p>A photograph showing a worker in a bright environment, wearing a red hard hat and a blue shirt, inspecting equipment on a table. The worker is kneeling next to the table, and the scene is well-lit. A timestamp in the bottom right corner reads "2023.10.8".</p>

26	GX-B1328/20-7-23043	2023. 10. 30	本次共检绝缘鞋4只，4只绝缘鞋合格。	
27	GX-B1328/20-7-23048	2023. 10. 31	本次共检绝缘手套2只，2只绝缘手套合格。	