


















序号	报告编号	发布日期	结论	影像资料
25	GX-B1598/24-6-24119	2024/11/8	实测钢丝绳有效截面积损失百分比最大为1.32%，小于5%为正常。	
26	GX-B1598/24-6-24120	2024/11/8	实测钢丝绳有效截面积损失百分比最大为1.86%，小于5%为正常。	

27	GX-B1598/24-6-24121	2024/11/7	实测钢丝绳有效截面积损失百分比最大为1.52%，小于5%为正常。	
28	GX-B1598/24-6-24122	2024/11/7	实测钢丝绳有效截面积损失百分比最大为1.66%，小于5%为正常。	
29	GX-B1598/24-6-24123	2024/11/7	实测钢丝绳有效截面积损失百分比最大为1.52%，小于5%为正常。	

30	GX-B1598/24-6-24124	2024/11/7	实测钢丝绳有效截面积损失百分比最大为1.65%，小于5%为正常。	
31	GX-B1598/24-6-24125	2024/11/7	实测钢丝绳有效截面积损失百分比最大为1.21%，小于5%为正常。	
32	GX-B1598/24-6-24126	2024/11/7	实测钢丝绳有效截面积损失百分比最大为2.23%，小于5%为正常。	

33	GX-B1598/24-6-24127	2024/11/7	实测钢丝绳有效截面积损失百分比最大为1.27%，小于5%为正常。	 <p>2024 10 29</p>
34	GX-B1598/24-6-24128	2024/11/7	实测钢丝绳有效截面积损失百分比最大为2.62%，小于5%为正常。	 <p>2024 10 29</p>
35	GX-B1598/24-6-24129	2024/11/8	实测钢丝绳有效截面积损失百分比最大为1.13%，小于5%为正常。	 <p>2024 10 29</p>

36	GX-B1598/24-6-24130	2024/11/8	实测钢丝绳有效截面积损失百分比最大为1.22%，小于5%为正常。	 <p>2024 10 29</p>
37	GX-B1598/24-6-24131	2024/11/8	实测钢丝绳有效截面积损失百分比最大为0.46%，小于5%为正常。	 <p>2024 10 30</p>
38	GX-B1598/24-6-24132	2024/11/8	实测钢丝绳有效截面积损失百分比最大为0.91%，小于5%为正常。	 <p>2024 10 30</p>

39	GX-B1598/24-6-24133	2024/11/8	实测钢丝绳有效截面积损失百分比最大为0.31%，小于5%为正常。	
40	GX-B1598/24-6-24134	2024/11/8	实测钢丝绳有效截面积损失百分比最大为1.84%，小于5%为正常。	
41	GX-B1598/24-6-24135	2024/11/8	实测钢丝绳有效截面积损失百分比最大为1.84%，小于5%为正常。	

42	GX-B1598/24-6-24136	2024/11/8	<p>实测钢丝绳有效截面损失百分比最大为2.25%，小于5%为正常。</p>	
43	GX-B1598/24-6-24137	2024/11/8	<p>实测钢丝绳有效截面损失百分比最大为1.60%，小于5%为正常。</p>	
44	GX-B1310/21-6-24344	2024/11/12	符合标准要求	

45	GX-B1310/21-6-24345	2024/11/12	符合标准要求	 <p>2024 10 17</p>	
46	GX-B1310/21-6-24349	2024/11/12	符合标准要求	 <p>2024 10 16</p>	
47	GX-B1310/21-6-24351	2024/11/12	符合标准要求	 <p>2024 10 17</p>	



48	GX-B1310/21-6-24340	2024/11/12	符合标准要求	
49	GX-B1310/21-6-24341	2024/11/12	符合标准要求	
50	GX-B1310/21-6-24342	2024/11/12	符合标准要求	

30	GX-B1310/21-6-24343	2024/11/12	符合标准要求	 <p>2024 10 17</p>	
31	GX-B1310/21-6-24346	2024/11/12	符合标准要求	 <p>2024 10 16</p>	
32	GX-B1310/21-6-24347	2024/11/12	符合标准要求	 <p>2024 10 16</p>	

33	GX-B1310/21-6-24348	2024/11/12	符合标准要求	 <p>2024 10 16</p>
34	GX-B1310/21-6-24352	2024/11/12	符合标准要求	 <p>2024 10 17</p>
35	GX-B1310/21-6-24350	2024/11/12	符合标准要求	 <p>2024 10 17</p>

36	GX-B1310/21-6-24353	2024/11/11	符合标准要求		 A photograph showing a worker in a red hard hat and blue uniform operating a green industrial machine. The worker is wearing white gloves and is focused on the task. The machine has a large flywheel and various components. The background is dark, suggesting an industrial setting. A date stamp '2024 10 24' is visible in the bottom right corner of the image.	
----	---------------------	------------	--------	--	--	--