

序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-2-24415	2025/1/2	符合标准要求。	 A worker in a red protective suit and helmet is inspecting a large, dark industrial component. The date 2024/11/26 is visible in the bottom right corner of the image.
2	GX-B1310/21-2-24416	2025/1/2	符合标准要求。	 A worker in a blue protective suit and helmet is inspecting a large, dark industrial component. The date 2024/11/28 is visible in the bottom right corner of the image.
3	GX-B1428/21-2-24415	2025/1/2	无缺陷迹痕显示。	 A worker in a blue protective suit and helmet is inspecting a large, dark industrial component. The date 2024/11/28 is visible in the bottom right corner of the image.

4	GX-B1428/21-2-24416	2025/1/2	无缺陷迹痕显示。		 A photograph showing a worker in a red protective suit and mask inspecting a large, dark, curved industrial component. The worker is standing to the left of the component, which is mounted on a structure. The component has a dark, possibly metallic or carbon fiber, surface with some internal structures visible. A date stamp '2024/11/26' is visible in the bottom right corner of the image.	
---	---------------------	----------	----------	--	--	--